



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					CS3/LPC22007916/Gqy3-1
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22007916/Gqy3 Date: 18/08/2022 30/12/2022 Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.	YN 9810A	Veh. Inspected	SJN 957Y		
Policy No.		Coverage (\$)	0.00		
Claim No.		Excess (\$)	0.00		
Assign From	GERALD KENNY LIM	Assign Date	18/08/2022 30/12/2022		
2. Vehicle Particulars & Condition					
Make & Model		c.c	0		
Engine No.	HIDDEN	Year of Reg.			
Chassis No.		Colour			
Odometer	-	Steering			
Brakes		Modification			
General					
3. Conditions of Tyres					
	Size	Make	Balance		
R/H Front Tyre			mm		
L/H Front Tyre			mm		
R/H Rear Tyre			mm		
L/H Rear Tyre			mm		
4. Description of Damages					
5. General Information					
Accident Date	16/08/2022	Inspection Date	19/08/2022		
Survey held at	Y2K AUDIO DESIGN 160 SIN MING DRIVE, #06-13, SIN MING AUTOCITY, SINGAPORE 575722				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					