



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC22010514/Uqy3m4-1 Date: 11/01/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 9769S	Veh. Inspected	FBS 7345K
Policy No.		Coverage (\$)	0.00
Claim No.	22/22/22/VC05/026448	Excess (\$)	0.00
Assign From	KENNY LIM	Assign Date	30/12/2022
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA NMAX	c.c	155
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MH3SG5680MJ079379	Colour	SILVER
Odometer	47647 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110-70-13	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	130-70-13	PIRELLI	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION & O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/10/2022	Inspection Date	25/10/2022
Survey held at	M 1 MOTORING 411 CHANGI ROAD SINGAPORE 419860		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	