

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Lee

Date: 03 Jan 2023

Preliminary Advice

Vehicle No	: SMW3361M	Accident Date	: 18/12/2022
Make	: NISSAN GTR	Policy No.	: DMPCSNW00024122200
Assignment Date	: 30/12/2022	Excess	: S\$3,500.00
Date of Inspection	: 30/12/2022	Est. Duration of Repair	: 30
Inspection At	: CH CHUAN HO PTE LTD (HQ) 160 SIN MING DRIVE, #07-09 SIN MING AUTO CITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Pending for investigation.

Repairer's Estimate (Gross)	:S\$	229,771.27
Revised Amount	:S\$	83,754.23
Check Items (Estimated)	:S\$	124,174.97
Total	:S\$	207,929.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	238,000.00
COE / PARF Rebate	:S\$	19,284.00
Salvage Value	:S\$	
Margin for Repair	:S\$	218,716.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Kindly advise the offer to repairer.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.