

CH CHUAN HO PTE LTD  
 SIN MING AUTO CITY  
 160 SIN MING DRIVE #07-09  
 SINGAPORE 575722

*Not Attached*  
*1 Day @*  
*Perman Alex Park*  
*'B' Bump*

ESTIMATE : SMW 3361 M

Vehicle & Document Information

Date: 29/12/2022  
 Vehicle No: SMW 3361 M  
 Make/Model: NISSAN / GTR

S/N	DESCRIPTION	Qty	Repalrer's Est	
1	REAR WINDSCREEN	1	\$ 2,500.00	
2	REAR WINDSCREEN MOULDING	1	\$ 244.00	
3	ROOF (INNER)	1	\$ 2,600.00	
4	ROOF TRIMMING (INNER)	1	\$ 1,250.00	
5	REAR SITS	2	\$ 9,179.00	
6	REAR SPEAKER CONSOLE	1	\$ 780.00	
7	FRONT SITS	2	\$ 11,800.00	
8	LEFT HAND DOOR PANEL	1	\$ 5,670.00	
9	RIGHT HAND DOOR PANEL	1	\$ 5,670.00	
10	FRONT DASHBOARD	1	\$ 4,560.00	
11	FRONT RADIO CONSOLE PANEL	1	\$ 1,575.00	
12	RIGHT HAND SPEAKER COVER	1	\$ 145.00	
13	LEFT HAND SPEAKER COVER	1	\$ 145.00	
14	RIGHT HAND SPEAKER	1	\$ 425.00	
15	LEFT HAND SPEAKER	1	\$ 425.00	
16	FRONT WINDSCREEN WITH MOULDING	1	\$ 3,250.00	
17	RIGHT HAND DOOR WINDOW	1	\$ 1,450.00	
18	LEFT HAND DOOR WINDOW	1	\$ 1,450.00	
19	RIGHT HAND FRONT SAFETY BELT WITH BUCKLE	1	\$ 1,275.00	
20	LEFT HAND FRONT SAFETY BELT WITH BUCKLE	1	\$ 1,275.00	
21	RIGHT HAND REAR SAFETY BELT WITH BUCKLE	1	\$ 758.00	
22	LEFT HAND REAR SAFETY BELT WITH BUCKLE	1	\$ 758.00	
23	GEAR NOB WITH GEAR STICK	1	\$ 2,734.50	
24	FRONT CENTER CONSOLE PANEL	1	\$ 965.00	
25	REAR DASHBOARD SPEAKER	2	\$ 474.00	
26	REAR DASHBOARD SPEAKER COVER	2	\$ 2,566.00	
27	HAND BRAKE	1	\$ 1,271.35	
28	STEERING COLUMN	1	\$ 5,295.00	
29	STERRING WHEEL	1	\$ 3,240.00	
30	RIGHT HAND REAR WINDOW GLASS	1	\$ 478.40	
31	RIGHT HAND REAR WINDOW GLASS MOULDING	1	\$ 53.84	
32	LEFT HAND REAR WINDOW GLASS	1	\$ 478.40	
33	LEFT HAND REAR WINDOW GLASS MOULDING	1	\$ 53.84	
34	WHOLE CAR INTERIOR LEATHER TRIMMING	1	\$ 2,400.00	
35	REAR, FRONT FLOOR	1	\$ 476.96	
36	REAR, REAR FLOOR	1	\$ 284.18	
37	REAR SENSOR MOUNTING	1	\$ 143.20	
38	BOLT PLATE	2	\$ 20.19	
39	REAR FLOOR REINFORCE-ANCHOR BELT	1	\$ 155.14	
40	FRONT FLOOR GUSSET RIGHT HAND REAR	1	\$ 93.52	
41	FRONT FLOOR GUSSET LEFT HAND REAR	1	\$ 93.52	
42	REAR FLOOR FRONT EXTENSION	1	\$ 253.84	
43	CARPET FRONT BRAKET	1	\$ 7.38	
44	INNER RIGHT HAND SILL	1	\$ 155.42	
45	INNER LEFT HAND SILL	1	\$ 155.42	
46	FRONT CENTER FLOOR	1	\$ 876.31	
47	FRONT RIGHT HAND FLOOR	1	\$ 780.38	
48	FRONT LEFT HAND FLOOR	1	\$ 780.38	
49	HEAT INSULATOR -FRONT FLOOR RGHT HAND	1	\$ 83.41	
50	HEAT INSULATOR - FRONT FLOOR	1	\$ 121.30	
51	HEAT INSULATOR - REAR FLOOR	1	\$ 315.41	
52	INSULATOR SET	3	\$ 327.39	

53	FRONT BUMPER GUARD	1	\$	104.04	X
54	FRONT UNDER COVER	1	\$	1,407.13	X
55	ENGINE LOWER COVER (REAR)	1	\$	352.61	?
56	ENGINE LOWER COVER (FRONT)	1	\$	1,946.82	?
57	FLOOR CARPET ASSEMBLY	1	\$	1,034.60	?
58	FLOOR SIDE SPACER	2	\$	173.10	?
59	FLOOR SIDE SPACER LEFT HAND	2	\$	191.01	?
60	LEFT HAND SPACER FRONT FLOOR TRIM	1	\$	18.90	?
61	RIGHT HAND SPACER FRONT FLOOR TRIM	1	\$	18.90	?
62	CARPET BRACKET	1	\$	5.03	?
63	LID ASSEMBLY FRONT FLOOR BOX	1	\$	183.46	?
64	RIGHT HAND STEP FRONT PLATE	1	\$	92.81	?
65	MEMBER ASSEMBLY - CROSS, REAR SEAT	1	\$	773.12	?
66	RIGHT HAND REAR MEMBER	1	\$	1,271.23	X
67	LEFT HAND REAR MEMBER	1	\$	1,271.23	X
68	SECOND CROSS REAR MEMBER 2ND	1	\$	285.47	?
69	MEMBER ASSEMBLY CROSS CENTER	1	\$	251.72	?
70	RIGHT HAND HOUSING ASSEMBLY FRONT STRUT WITH FRONT SIDE MEMBER	1	\$	6,596.01	?
71	LEFT HAND HOUSING ASSEMBLY FRONT STRUT WITH FRONT SIDE MEMBER	1	\$	6,596.01	?
72	RIGHT HAND FRONT PILLAR BRACE	1	\$	304.21	?
73	LEFT HAND FRONT PILLAR BRACE	1	\$	304.21	?
74	RIGHT HAND SIDE ROOF INNER RAIL	1	\$	315.41	?
75	LEFT HAND SIDE ROOF INNER RAIL	1	\$	315.41	?
76	RIGHT HAND SILL OUTER REINFORCEMENT	1	\$	339.39	?
77	LEFT HAND SILL OUTER REINFORCEMENT	1	\$	339.39	X
78	RIGHT HAND REINFORCEMENT ASSEMBLY LOCK PILLAR	1	\$	313.80	?
79	LEFT HAND REINFORCEMENT ASSEMBLY LOCK PILLAR	1	\$	313.80	?
80	LEFT HAND LOCK INNER PILLAR ASSEMBLY	1	\$	267.44	?
81	RIGHT HAND LOCK INNER PILLAR ASSEMBLY	1	\$	267.44	?
82	RIGHT HAND BODY ASSEMBLY	1	\$	5,923.91	?
83	LEFT HAND BODY ASSEMBLY	1	\$	5,923.91	?
84	RIGHT HAND WEATHER STRIP	1	\$	270.63	?
85	LEFT HAND WEATHER STRIP	1	\$	270.63	?
86	RIGHT HAND RETAINER WEATHERSTRIP	1	\$	213.08	?
87	LEFT HAND RETAINER WEATHERSTRIP	1	\$	213.08	?
88	RIGHT HAND MOULDING ROOF DRIP	1	\$	73.65	?
89	LEFT HAND MOULDING ROOF DRIP	1	\$	73.65	?
90	RIGHT HAND REAR WHEEL HOUSE PROTECTOR	1	\$	214.68	?
91	LEFT HAND REAR WHEEL HOUSE PROTECTOR	1	\$	214.68	?
92	RIGHT HAND PROTECTOR-BODY SIDE SILL	1	\$	632.95	?
93	LEFT HAND PROTECTOR-BODY SIDE SILL	1	\$	632.95	?
94	SIDE SILL REAR PROTECTOR	2	\$	85.82	?
95	LEFT HAND FRONT PILLAR FINISHER	1	\$	919.48	?
96	RIGHT HAND FRONT PILLAR FINISHER	1	\$	919.48	?
97	RIGHT HAND REAR FINISHER	1	\$	851.45	?
98	LEFT HAND REAR FINISHER	1	\$	851.45	?
99	RIGHT HAND FRONT PILLAR GARNISH ASSEMBLY	1	\$	310.61	?
100	LEFT HAND FRONT PILLAR GARNISH ASSEMBLY	1	\$	310.61	?
101	RIGHT HAND FRONT BODY SIDE WELT	1	\$	117.45	?
102	LEFT HAND FRONT BODY SIDE WELT	1	\$	117.45	?
103	RIGHT HAND REAR PILLAR FINISHER	1	\$	188.61	?
104	LEFT HAND REAR PILLAR FINISHER	1	\$	188.61	?
105	RIGHT HAND FRONT KICKING OUTER PLATE	1	\$	167.66	?
106	LEFT HAND FRONT KICKING OUTER PLATE	1	\$	167.66	?
107	RIGHT HAND FRONT KICKING PLATE	1	\$	152.01	?
108	LEFT HAND FRONT KICKING PLATE	1	\$	152.01	?
109	LEFT HAND MODULE ASSEMBLY-CURTAIN AIR BAG	1	\$	728.58	?
110	RIGHT HAND MODULE ASSEMBLY-CURTAIN AIRBAG	1	\$	728.58	?
111	RIGHT HAND REAR FENDER	1	\$	1,909.29	X
112	LEFT HAND REAR FENDER	1	\$	1,990.72	X
113	FUEL LID ASSEMBLY	1	\$	496.51	

114	PARCEL SHELF ASSEMBLY -W/REAR WAIST	1	\$	635.61	?
115	REINFORCE-PARCEL SHELF	1	\$	83.41	?
116	REAR UPPER PANEL	1	\$	1,014.54	X
117	RIGHT HAND FRONT DOOR	1	\$	3,039.93	?
118	LEFT HAND FRONT DOOR	1	\$	2,923.45	?
119	LEFT HAND DOOR WEATHER STRIP	1	\$	256.25	—
120	RIGHT HAND DOOR WEATHER STRIP	1	\$	256.25	—
121	LEFT HAND FRONT DOOR OUTSIDE MOLDING ASSEMBLY	1	\$	174.54	?
122	RIGHT HAND FRONT DOOR OUTSIDE MOLDING ASSEMBLY	1	\$	174.54	?
123	LEFT HAND FRONTDOOR MODULE BASE ASSEMBLY	1	\$	408.14	?
124	RIGHT HAND FRONT DOOR MODULE BASE ASSEMBLY	1	\$	408.14	?
125	LEFT HAND FRONT DOOR LOWER HINGE ASSEMBLY	2	\$	228.56	X
126	RIGHT HAND FRONT DOOR LOWER HINGE ASSEMBLY	2	\$	228.56	X
127	RIGHT HAND DOOR CORNER PIECE	1	\$	132.83	?
128	LEFT HAND DOOR CORNER PIECE	1	\$	132.83	?
129	LEFT HAND DOOR INNER WAIST FRONT REINFORCEMENT	1	\$	184.78	?
130	RIGHT HAND DOOR INNER WAIST FRONT REINFORCEMENT	1	\$	184.78	?
131	LEFT HAND DOOR PARTING SEAL	1	\$	125.03	?
132	RIGHT HAND DOOR PARTING SEAL	1	\$	125.03	?
133	RIGHT HAND FRONT DOOR ARM REST	1	\$	219.48	—
134	LEFT HAND FRONT DOOR ARM REST	1	\$	219.48	—
135	RIGHT HAND FRONT DOOR CAP ASSIST GRIP	1	\$	277.03	—
136	LEFT HAND FRONT DOOR CAP ASSIST GRIP	1	\$	277.03	—
137	LEFT HAND FRONT DOOR POWER WINDOW SWITCH	1	\$	124.65	—
138	RIGHT HAND FRONT DOOR POWER WINDOW SWITCH	1	\$	124.65	—
139	LEFT HAND FRONT DOOR PULL HANDLE	1	\$	140.02	—
140	RIGHT HAND FRONT DOOR PULL HANDLE	1	\$	140.02	—
141	LEFT HAND DOOR INNER PANEL	1	\$	2,806.13	—
142	RIGHT HAND DOOR INNER PANEL	1	\$	2,806.13	—
143	REAR BOOT TRUNK FLOORING	1	\$	721.32	?
144	REAR BOOT TRUNK FRONT ASSEMBLY	1	\$	296.94	?
145	RIGHT HAND REAR WHEEL HOUSING	1	\$	188.91	?
146	LEFT HAND REAR LUGGAGE SIDE FINISHER	1	\$	303.31	?
147	REAR BOOT TRUNK LID FINISHER	1	\$	222.05	?
148	REAR BOOT TRUNK FLOOR SPACER	1	\$	136.66	?
149	REAR BOOT TRUNK PLATE	1	\$	123.76	?
150	REAR BOOT TRUNK LID	1	\$	2,127.71	X
151	LEFT HAND REAR BOOT TRUNK LID HINGE	1	\$	168.36	X
152	RIGHT HAND REAR BOOT TRUNK LID HINGE	1	\$	168.36	X
153	REAR BOOT TRUNK LID HYDRAULIC ASSEMBLY	2	\$	314.76	?
154	REAR BOOT TRUNK LID LOCK STRIKER ASSEMBLY	1	\$	85.04	?
155	REAR BOOT TRUNK LID LOCK ASSEMBLY	1	\$	141.44	?
156	REAR BOOT TRUNK LID WEATHER STRIP	1	\$	193.21	?
157	REAR VIEW MIRROR	1	\$	189.71	—
158	LEFT HAND FRONT DOOR CORNER INNER COVER	1	\$	133.95	?
159	RIGHT HAND FRONT DOOR CORNER INNER COVER	1	\$	133.95	?
160	LEFT HAND FRONT DOOR MIRROR ASSEMBLY	1	\$	545.47	X
161	RIGHT HAND FRONT DOOR MIRROR ASSEMBLY	1	\$	545.47	X
162	LEFT HAND FRONT SUN VISOR	1	\$	276.22	—
163	RIGHT HAND FRONT SUN VISOR	1	\$	276.22	—
164	FRONT CENTER CONSOLE CUP HOLDER ASSEMBLY	1	\$	184.61	?
165	FRONT CENTER CONSOLE COIN POCKET	1	\$	112.77	?
166	FRONT CENTER CONSOLE BOX FLOOR	1	\$	780.27	?
167	FRONT CENTER CONSOLE BODY	1	\$	445.09	?
168	FRONT CENTER CONSOLE BOX LID	1	\$	273.07	?
169	FRONT CENTER INNER CONSOLE BOX ASSEMBLY	1	\$	157.53	?
170	FRONT CENTER CONSOLE BOOT	1	\$	236.40	?
171	FRONT CENTER CONSOLE INDICATOR FINISHER	1	\$	373.41	?
172	FRONT CENTER CONSOLE REAR ASSEMBLY	1	\$	202.46	?
173	FRONT CENTER CONSOLE REAR CUP HOLDER	1	\$	98.59	?

<b>Total :</b>	\$	161,992.06
<b>10%</b>	\$	16,199.21
<b>Parts Total :</b>	\$	178,191.27

S/N	SPECIAL NET ITEM	Qty	Repairer's Est
1	WHOLE CAR 3M CRYSTALLINE WINDOW TINTING	(Insured)	\$ 3,800.00
2	STEERING WHEEL CARBON FIBRE		\$ 15,000.00
3	FRONT CENTER PANEL CARBON FIBRE		\$ 8,000.00
4	REAR CENTER SPEAKER CARBON FIBRE		\$ 7,800.00
5	THINKWARE IN-CAR CAMERA		\$ 1,200.00
Labour Total :			\$ 35,800.00
10%			\$ 3,580.00
Total :			\$ 39,380.00

? } Check Insured?  
? }  
? }  
? }

S/N	LABOUR	Qty	Repairer's Est
1	LABOUR TO REPLACE BODY ITEMS		\$ 3,000.00
2	LABOUR TO CONDUCT WIRING & ELECTRICAL FAULT TEST		\$ 500.00
3	LABOUR TO REPLACE FRONT WINDSCREEN, REAR WINDSCREEN AND 2X REAR WINDOW		\$ 800.00
4	LABOUR TO REPLACE ROOF LINEN, CAR INTERIOR LEATHER AND ALL CAR INTERIOR TRIMMING		\$ 1,200.00
5	LABOUR TO INSTALL ALL RADIO SPEAKERS, IN-CAR CAMERAS AND REWIRING		\$ 400.00
6	LABOUR TO DE-RUST AND PRIME ALL INTERIOR STEEL PANEL		\$ 2,800.00
7	SPRAY PAINT ROOF, 2X A-PILLAR, REAR BOOT COVER, RIGHT HAND REAR FENDER AND LEFT HAND REAR FENDER		\$ 3,500.00
Labour Total :			\$ 12,200.00
Parts & labour total			\$ 229,771.27
Total :			\$ 229,771.27

1000  
900  
480  
400  
180  
800  
1750

CH CHUAN HO PTE LTD




**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: