

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURAN	NCE PTE LTD	Ref:	CS/LIP22013028/Avy3m4	
	51 CLUB STREET, LIBERTY HOUSES	#03-00 INGAPORE 069428	Date:	23/03/2023	
			Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNE 2577Y	Veh. Inspected	SGY 1089Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	AVS23/0041	Excess (\$)	0.00	
	Assign From	ANDY SEAH	Assign Date	30/12/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI LANCER	c.c	1584	
	Engine No.	HIDDEN	Year of Reg.	-	
	Chassis No.	JMYSNCS3A7U010044	Colour	SILVER	
	Odometer	227466 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/60 R15	TRIANGLE	6 mm	
	L/H Front Tyre	195/60 R15	TRIANGLE	6 mm	
	R/H Rear Tyre	195/60 R15	TRIANGLE	6 mm	
	L/H Rear Tyre	195/60 R15	TRIANGLE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	27/12/2022	Inspection Date	30/12/2022	
	Survey held at	KANG CAR REPAIRERS PTE LTD			
		NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKI SINGAPORE 417883	Т		
5a. Remarks					
	A)REGISTRATION DATE: 17 SEP 2007 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			