

**FOCUS AUTO PTE LTD**

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: [claims@focusauto.com.sg](mailto:claims@focusauto.com.sg)**ALLIANZ INSURANCE SINGAPORE PTE LTD**

79 Robinson Road

#09-01

Singapore 068897

ATTN : Motor Claim Department

Your Ref No. : **GBG 1337 L**Claim Type : **THIRD PARTY**

Accident Date : 15/12/2022

Estimate No : E22120084

Date : 30/12/2022

Veh Reg No : **SLQ 5115 M**Make / Model : **HONDA VEZEL 1.5G CVT**

Chassis No. : RV31007688

Engine No. : L15Z1009094

Reg. Date : 29/11/2022

4 Days.  
P/P  
Define part price  
Guy As  
30/12/22

**Estimate Repair Cost to Vehicle No : SLQ 5115 M**

|                                            | Quantity | Unit | Price<br>S\$ | Amount<br>S\$   |
|--------------------------------------------|----------|------|--------------|-----------------|
| <b>LIST PRICE</b>                          |          |      |              |                 |
| 1 Front Bonnet / BT                        | 1        | PCS  | 1,037.20     | 1,037.20        |
| 2 Front Bonnet Lock X ~ N                  | 1        | PCS  | 89.20        | 89.20           |
| 3 Front Bonnet Hinge / BT                  | 1-2      | PCS  | 49.50        | 99.00           |
| 4 Front Headlamp RH / cut                  | 1        | PCS  | 2,350.20     | 2,350.20        |
| 5 Front Grille                             | 1        | PCS  | 385.60       | 385.60          |
| 6 Front Grille Moulding ?                  | 1        | PCS  | 148.50       | 148.50          |
| 7 Front Grille Garnish / cut               | 1        | PCS  | 298.40       | 298.40          |
| 8 Front Bumper / De                        | 1        | PCS  | 1,350.00     | 1,350.00        |
| 9 Front Bumper Reinforcement ?             | 1        | PCS  | 346.20       | 346.20          |
| 10 Front Bumper Towing Cover / cut         | 1        | PCS  | 50.40        | 50.40           |
| 11 Front Bumper Lower Spoiler / cut        | 1        | PCS  | 586.40       | 586.40          |
| 12 Front Bumper Lower Grille ?             | 1        | PCS  | 389.40       | 389.40          |
| 13 Front Bumper Side Grille - RH ?         | 1        | PCS  | 226.40       | 226.40          |
| 14 Front Bumper Side Grille Garnish - RH ? | 1        | PCS  | 126.40       | 126.40          |
| 15 Front Bumper Side Retainer - RH ?       | 1        | PCS  | 38.60        | 38.60           |
| 16 Front Headlamp Lower Bracket - RH ?     | 1        | PCS  | 146.20       | 146.20          |
| 17 Front Fender Protector - RH / BR        | 1        | PCS  | 264.20       | 264.20          |
| <b>TOTAL A :</b>                           |          |      |              | <b>7,932.30</b> |
| <b>DISCOUNT 20% :</b>                      |          |      |              | <b>1,586.46</b> |
| <b>SUB-TOTAL :</b>                         |          |      |              | <b>6,345.84</b> |

**LABOUR CHARGES**

- 1 Panel Beating
  - 2 Check Wiring
  - 3 Rust Proofing
  - 4 Spray Painting
- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

S\$

S\$

500 950.00  
30 60.00  
75 60.00  
75 850.00

|                                |                 |
|--------------------------------|-----------------|
| <b>TOTAL B :</b>               | <b>1,920.00</b> |
| <b>GRAND TOTAL A &amp; B :</b> | <b>8,265.84</b> |

**FOR FOCUS AUTO PTE LTD**

Jenny Koh  
Claims Executive  
HP: 8139 9800