

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial Vehicles

29/12/2022 @ 12pm - 1pm

Quotation

Non binding - Preview

Page

1/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
NG
WEI XIAN
(HUANG WEIXIAN)
827 JURONG WEST STREET 81
#07-284
Singapore 640827

Document no.
Document date 23-12-2022
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2022037253/ 1
Job order date 22-12-2022
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMN6704K	5E33MDP0	23-08-2019	TMBBC7NE1K0171758	Octavia Ambition + 1.4 I TSI 110kW DSG	79,536

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR				#1	200.00	214.00
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	360.00	385.20
9801B001	TO ALIGN LED HEADLIGHT ?				#1	100.00	107.00
5E0823031B	Hood	1	pcs.	1,810.86	28.00%	1,303.82	1,395.09
5E0823717	Clip	10	pcs.	0.59	28.00%	4.25	4.55
5E0823186E	Hood Latch	1	pcs.	94.30	28.00%	67.90	72.65
	BONNET LATCH						
5E0823509B	Hood Latch	1	pcs.	115.57	28.00%	83.21	89.03
	BONNET LOCK						
3V0853621A FOD	Skoda Embl	1	pcs.	70.22	28.00%	50.56	54.10
5E0807221P	Cover For	1	pcs.	1,385.13	28.00%	997.29	1,067.10
	FRT BUMPER						
5E0919485G	Sensor bracket	1	pcs.	13.52	28.00%	9.73	10.41
5E0919486G	Sensor bracket	1	pcs.	13.52	28.00%	9.73	10.41
5E0919485F	Sensor bracket	1	pcs.	13.52	28.00%	9.73	10.41
5E0919486F	Sensor bracket	1	pcs.	13.52	28.00%	9.73	10.41
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	28.00%	61.88	66.21
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	28.00%	49.57	53.04
5E0807611D 9B9	End Plate	1	pcs.	164.69	28.00%	118.58	126.88
	BUMPER LOWER ELEMENT						
5E0853653A 9B9	Unbekannt	1	pcs.	259.72	28.00%	187.00	200.09
	RADIATOR GRILLE						
5E0853761C 2ZZ	Cover Stri	1	pcs.	278.38	28.00%	200.43	214.46
	RADIATOR GRILLE CHROME						
701010002AA	Sticker *Overfilled Engin	1	pcs.	16.43	28.00%	11.83	12.66
701010043B	Sticker *Oil Comply With	1	pcs.	26.52	28.00%	19.09	20.43
5Q0010008D	Sticker *Ac *Refrigeran	1	pcs.	18.87	28.00%	13.59	14.54
5E0807723A	Support Pa	1	pcs.	56.63	28.00%	40.77	43.62
	RADIATOR GRILLE INNER BRACKET LH						
5E0807724A	Support Pa	1	pcs.	56.63	28.00%	40.77	43.62
	RADIATOR GRILLE INNER BRACKET RH						
5E0853677J 9B9	Cooling Ai	1	pcs.	122.15	28.00%	87.95	94.11
	BUMPER CTR LOWER GRILLE						
5E0807681F 9B9	Cover For	1	pcs.	42.03	28.00%	30.26	32.38
	BUMPER LOWER GRILLE LH						
5E0807682F 9B9	Cover For	1	pcs.	42.03	28.00%	30.26	32.38
	BUMPER LOWER GRILLE RH						
5E2941015E	Unbekannt	1	pcs.	2,189.09	28.00%	1,576.14	1,686.47
	LHS H/LAMP						
5E2941016E	Unbekannt	1	pcs.	2,189.08	28.00%	1,576.14	1,686.47
	RHS H/LAMP						
5E0807109F	Reinforcem	1	pcs.	796.58	28.00%	573.54	613.69
5E0807248D	Buffer	1	pcs.	60.86	28.00%	43.82	46.89
	REINFORCEMENT FOAM						

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 2/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
NG
WEI XIAN
(HUANG WEIXIAN)
827 JURONG WEST STREET 81
#07-284
Singapore 640827

Document no.
Document date 23-12-2022
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2022037253/ 1
Job order date 22-12-2022
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMN6704K	5E33MDP0	23-08-2019	TMBBC7NE1K0171758	Octavia Ambition + 1.4 I TSI 110kW DSG	79,536

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	LABOUR	12	pcs.	560.00	#1 1120	2,240.00	2,396.80
	SPRAY PAINT	12	pcs.	530.00	#1 1060	2,220.00	2,268.40
	FRT NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	ALLIANZ OD						
	DOA: 20/12/2022						
	EXCESS:						
	SURVEY BY:						

Quotation valid till 29-12-2022

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	660.00	11,647.57	2,802.97	7%	861.53	2,802.97	12,307.57	13,169.10
Total	660.00	11,647.57	2,802.97		861.53	2,802.97	12,307.57	13,169.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

Customer

Service Advisor

Resu
Hp 90010068
4 days
29/12/22 @ 1200
EXCESS: TBA

Repair

Resu before part

All invoices are denominated in SGD, unless otherwise stated.

Front
Bumper, Bonnet