

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 03 Jan 2023

**Preliminary Advice**

Vehicle No	: SMN6704K	Accident Date	: 20/12/2022
Make	: SKODA OCTAVIA	Policy No.	: -
Assignment Date	: 03/01/2023	Excess	: S\$0.00
Date of Inspection	: 29/12/2022	Est. Duration of Repair	: 4 DAYS
Inspection At	: SKODA CENTRE SINGAPORE		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,307.57
Revised Amount	:S\$	5,557.80
Check Items (Estimated)	:S\$	4,509.25
Total	:S\$	10,067.05

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	40,779.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,221.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by Part Repair. The workshop is the agent workshop.
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.