



WTS Engineering Pte Ltd

YOUR REF: 2022 22008885/KC-SMW5676S
OUR REF: JW/1222/073

6 March 2023

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Attention: Motor Claims Department

WITHOUT PREJUDICE

Dear Sir,

ACCIDENT INVOLVING SMM5676S WITH OUR VEHICLE PD590C ON 14/12/2022.

We refer to the above accident and understand that you are the insurer of **SMM5676S**.

From our investigation, we are of opinion that the accident arose as a result of your insured's negligent driving.

Our loss in this connection comprises the following:

1. Cost Of Repairs	\$	702.00
2. 3 Days Loss of Use	\$	1,050.00
3. TP Insurer Enquiry	\$	2.00

Total:	\$	1,754.00
---------------	-----------	-----------------

Please let us know whether you are prepared to admit liability and reimburse our loss in full within the next two weeks on receipt of this letter otherwise we will proceed the matters legally which we will recourse the costs incurred to you.

Please acknowledge receipt of the above letter.

Thank you.

Yours faithfully,

Lim Xin Yi
Claims Department
Direct Line : (65) 6559 8954
Facsimile : (65) 6898 2394
Email : xinyi.lim@woodlandstransport.com.sg

WTS Engineering Pte Ltd

8, Gul Circle, Singapore 629564 Tel: 6 559 8988 Fax: 6 898 2394

URL: www.woodlandstransport.com.sg

Company Registration Number : 200505706E






WTS Engineering Pte Ltd

From : Workshop Department

M/S : Woodlands Transport Service Pte Ltd
No 8 Gul Circle
Singapore 629564

Date : 6-Mar-23
No: 0323/1194

S/n	Description	Unit	Amount
	Repair cost of PD590C Accident Date: 14/12/2022 Repair works took 3 days Cost of repair inclusive of spray paint		\$ 650.00
	Add 8% GST		\$ 52.00
	SGD: Seven Hundred and Two Dollars Only		
		Total	\$ 702.00


Authorised Signature

WTS Engineering Pte Ltd

8, Gul Circle, Singapore 629564 Tel: 6 559 8988 Fax: 6 898 2394 [URL:www.woodlandstransport.com.sg](http://www.woodlandstransport.com.sg)

Company Registration Number : 200505706E

