



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22010592/Dqy3m4-1 Date: 09/01/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 2574S	Veh. Inspected	XD 2756J	
Policy No.		Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/026461	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	31/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FP51	c.c	12882	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	FP51JDA00616	Colour	BLUE	
Odometer	230721 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	GOODYEAR	4 mm	
L/H Front Tyre	295/80 R22.5	GOODYEAR	4 mm	
R/H Rear Tyre	295/80 R22.5	GOODYEAR	4 mm	
L/H Rear Tyre	295/80 R22.5	GOODYEAR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/10/2022	Inspection Date	26/10/2022	
Survey held at	REDANTS ENGINEERING PTE LTD 10 BUROH STREET #04-26/29 WEST CONNECT BUILDING SINGAPORE 627564			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	