

653c

## TOTAL

## Accident Repair Estimate

**ACCIDENT DATE:** 30-Dec-22

**BUS REGISTRATION NUMBER:** SBS6665T

ACCIDENT TIME: 1201 HRS.

BUS TYPE: WSD

ACCIDENT REPORT NUMBER: 44925

DATE OF SURVEY:

3RD PARTY CLAIM AGAINST: SMB5074P

**SECTION A :**

### PARTS & MATERIAL COST

| Part or Item Description              | Quantity | Total Cost |
|---------------------------------------|----------|------------|
| OUTSIDE REARVIEW MIRROR N/S <i>CR</i> | 1        | \$1,440.40 |
|                                       |          |            |
|                                       |          |            |
|                                       |          |            |
|                                       |          |            |
|                                       |          |            |
|                                       |          |            |
|                                       |          |            |
|                                       |          |            |
|                                       |          |            |
| TOTAL PARTS & MATERIAL COST           |          | \$1,440.40 |

### SECTION B:

**ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)**

|                                                                |                 |
|----------------------------------------------------------------|-----------------|
| To Assess/ Remove / Replace / Repair Damaged Parts by Workshop | \$376.00        |
| To Remove / Replace / Repair Damaged Parts by Contractor       |                 |
| To Remove/ Replace/ Repair Damaged Advertisement Panel         |                 |
| <b>TOTAL LABOUR COST</b>                                       | <b>\$376.00</b> |

### SECTION C:

## SUMMARY

|                                                                   |   |            |
|-------------------------------------------------------------------|---|------------|
| Total Repair Costs                                                |   | \$1,816.40 |
| Total Downtime (Days)                                             | 1 | \$378.66   |
| Towing Cost                                                       |   | \$0.00     |
| Total Overhead Costs                                              |   |            |
| *Please kindly note that the downtime (days) is just an estimate. |   |            |

*\*Please kindly note that the downtime (days) is just an estimate.*

*\*Please undersign to acknowledge this repair estimate.*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

Date:

Acknowledge By

Surveyor Name

Contact No

Email Address

Page.

I Synthese Rasu

90010068

rasul@lkkauto.com

04/01/23 @ 1535 - 1 day