

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Priya

Date: 11 Jan 2023

Preliminary Advice

Vehicle No	: SLR2784X	Accident Date	: 31/12/2022
Make	: MITSUBISHI ATTRAGE	Policy No.	: D19MPC0003729-03
Assignment Date	: 04/01/2023	Excess	: S\$0.00
Date of Inspection	: 10/01/2023	Est. Duration of Repair	: 4
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES) BLK 9006 #01-200 TAMPINES ST 93 SINGAPORE 528840		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,823.20
Revised Amount	:S\$	4,101.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,101.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	15,304.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,696.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.