



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0013/2023/EQ  
**DATE** : 6-Jan-23  
**WIP** : 57643

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/1/2023**  
**YOUR INSURED VEH NO : SME 5670 C**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MS KOO YI KHIM  
**ADDRESS** : 12Q CHANCERY HILL ROAD  
SINGAPORE 307403  
**TELEPHONE** : HP +65 81612010  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : SP2000616092  
**VEHICLE NO** : **SMQ 7525 M**  
**MODEL CODE** : AUDI Q3 1.4 TFSI S-TRONIC  
**MODEL YEAR** : 29/11/2019  
**ENGINE NO** : CZD 887132  
**CHASSIS NO** : WAUZZZF34L1025806  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 31-Dec-22  
**PLACE OF ACCIDENT** : CAR PARK OF SHAW CENTRE

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 7525 M**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODUE.	S/N \$ 400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,500.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 5,972.00</b>	

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 7525 M**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
1	FRONT BUMPER	1	\$ 1,073.00	
2	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 66.00	
3	FRONT BUMPER GRILLE - RH	1	\$ 124.00	
4	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00	
5	FRONT BUMPER SPOILER	1	\$ 426.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00	
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00	
8	FRONT WHEEL COVER - LH / RH	2	\$ 566.00	
9	FRONT FENDER - RH	1	\$ 1,445.00	
10	FRONT FENDER BRACE - RH	1	\$ 98.00	
11	FRONT FENDER BRACKET - RH	1	\$ 39.00	
12	FRONT WHEEL HOUSING LINER	1	\$ 260.00	
13	FRONT FENDER COVER - RH	1	\$ 18.00	
14	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 22.00	
15	HEADLIGHT MOUNTING - RH	1	\$ 132.00	
16	HEADLIGHT - RH	1	\$ 5,952.00	
17	LIFT CYLINDER - RH	1	\$ 231.00	
18	LIFT CYLINDER HOSE	1	\$ 92.00	
19	SUNDRIES		\$ 500.00	
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 11,470.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 5,972.00</b>	
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 17,442.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT