



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:VALE OH		Ref: CC4/ASM23000122/Spa3q2 Date: 03/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6991H	Veh. Inspected	SJU 4771C
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S3M04HDI	Excess (\$)	0.00
Assign From		Assign Date	04/01/2023
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GB31036164	Colour	BLACK
Odometer	259488 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	TOURADOR	6 mm
L/H Front Tyre	205/55 R16	TOURADOR	6 mm
R/H Rear Tyre	205/55 R16	TOURADOR	5 mm
L/H Rear Tyre	205/55 R16	TOURADOR	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/12/2022	Inspection Date	04/01/2023
Survey held at	CHIA AUTO SERVICES PTE LTD 23 KAKI BUKIT AVENUE 4 #02-03A AAS KAKI BUKIT CENTRE SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	