Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)

Sent:Friday, 6 January 2023 1:56 PMTo:tlmautomobile@tlmotor.com.sg; SURSubject:SLB 9840E-DOA: 3/1/2023 (HL OD)

Dear Sir,

As instructed by our client, please proceed to repair the **insured vehicle SLB 9840E. Lump Sum Repair**. **(Excess \$625/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)