

Not Authorised
6/2/23
1/5 \$ 3500 / 3 days.

SPEEDWERKZ PRIVATE LIMITED
1 KAKI BUKIT AVENUE 6, #01-73, AUTOBAY, SINGAPORE 417883
Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER : BGT6034
MAKE & MODEL: TOYOTA UNSER
DOA: 27/12/2022
CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BOOT COVER	1	\$1,865.00	
REAR BOOT REFLECTOR @398	2	\$796.00	
REAR BOOT RUBBER TOP GARNISH	1	\$82.70	
REAR BOOT RUBBER	1	\$328.50	
REAR BOOT LOCK	1	\$265.10	
REAR LOCK CATCH	1	\$128.00	
REAR BOOT HINGE @85.20	2	\$170.40	
REAR BOOT ABSORBER @285.00	2	\$570.00	
REAR BOOT CENTRE GARNISH	1	\$176.50	
REAR BOOT INNER BOARD	1	\$315.20	
REAR BOOT GLASS MOULDING	1	\$82.70	
REAR WINDSCREEN GLASS	1	\$1,243.00	
REAR BOOT LOCK ACTUATOR	1	\$410.60	
REAR BOOT WIPER MOTOR	1	\$498.50	
REAR BOOT EMBLEM LOGO	1	\$65.20	
REAR END PANEL INNER	1	\$912.70	
REAR END PANEL OUTER	1	\$486.50	
REAR THIRD BRAKE LIGHT	1	\$410.40	
REAR FLOOR BOARD PANEL	1	\$2,381.40	
REAR SIDE PANEL @1813.60	2	\$3,627.20	
REAR BUMPER	1	\$898.00	
REAR BUMPER SIDE RETAINER @60.80	2	\$121.60	
REAR BUMPER LOWER SUPPORT BRACKET @56.20	4	\$224.80	
REAR BUMPER REINFORCEMENT BEAM	1	\$768.00	
REAR NUMBER PLATE LAMP @65.60	2	\$131.20	
REAR TAILLAMP @752.30	2	\$1,504.60	
REAR TAILLAMP PANEL @282.70	2	\$565.40	
REAR EXHAUST SILENCER	1	\$825.00	
REAR EXHAUST RUBBER @58.70	2	\$117.40	
REAR SPARE TYRE CARRIER	1	\$412.10	

25%
Less 20 %
Sub Total

\$20,383.70
\$4,076.74
\$16,306.96

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR NUMBER PLATE	1	\$45.00	
REAR BUMPER CLIP	1	\$50.00	
REAR WINDSCREEN GLASS SEALANT	1	\$120.00	
REVERSING SENSOR	1	\$450.00	
Sub Total		\$665.00	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$100.00	
APPLY ANTI RUST CHEMICAL		\$250.00	
REMOVE AND REFIX REAR WINDSCREEN GLASS		\$150.00	
REMOVE AND REFIX, RENEW REAR EXHAUST PIPE		\$150.00	
REMOVE AND RENEW REVERSING SENSOR		\$150.00	
LABOUR CHARGE KNOCK DENTS ON REAR DAMAGE PORTION CUT, WELDING AND RENEW PART		\$2,200.00	

TO SPRAY PAINT AFFECTED PORTION		\$1,800.00	600
	Sub Total	<u>\$4,800.00</u>	

Grand Total \$21,771.96

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 3844.6
 257
2958.45
 270