



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	R	ef:	CS3/ASM23000165/Kvp3
	8 SHENTON WAY AXA TOWERSING		D	ate:	05/01/2023
			С	ode:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 8681G	Veh. Inspected		SLF 6770Y
	Policy No.		Coverage (\$)		0.00
	Claim No.	S3M04HFN	Excess (\$)		0.00
	Assign From	LOH CYNTHIA	Assign Date		05/01/2023
2.	Vehicle Particulars & Condition				
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.	Colour			
	Odometer	Steering			
	Brakes	Modification			
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	31/12/2022	Inspection Date		06/01/2023
	Survey held at KUM CHEW MOTOR WORKSHOP				
		160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				