



3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	40 x	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE REAR CAMERA	\$ 100.00	80 x	
7	TO REMOVE UPHOLSTERY	\$ 150.00	X	
8	TC TRANSFER TAILGATE FITTINGS	\$ 150.00	60 x	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	120 x	

TOTAL: \$ 3,680.00

580

**ESTIMATE REPORT**

TOTAL PARTS COST: \$ 6,742.90  
 TOTAL LABOUR COST: \$ 3,680.00  
 TOTAL REPAIR COST: \$ 10,422.90

total. 3371.40  
 1/s: 2.7K.

**APPROVED DETAILS**

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

2,700  
 3 days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date: