



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME: India International Insurance Pte Ltd
COMPANY NAME: India International Insurance Pte Ltd
STREET ADDRESS: 64 Cecil Street, #04/#05-02, IOB Building
POSTAL CODE: Singapore 049711
PHONE: 6347 6100

DATE: 5/1/2023

REF: SKW8985D
VEHICLE NO.: SKW8985D
MAKE: TOYOTA
MODEL: COROLLA
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REFIT FRONT & REAR DOOR P/WINDOW GLASS, REGULATOR & CHANNEL	1		\$200.00	\$ 200.00	60	\$ 200.00
2	TO DO ELECTRICAL 4 WHEEL ALIGNMENT	1		\$100.00	\$ 100.00	20	\$ 100.00
3	TO PROVIDE LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS, CUT & WELD IF NECESSARY AND REALIGNMENT	1		\$800.00	\$ 800.00	500	\$ 800.00
4	TO PROVIDE LABOUR & MATERIAL TO PAINT NEW PARTS & PANELS	1		\$1,000.00	\$ 1,000.00	600	\$ 1,000.00
PARTS							
1	FRONT RH FENDER	1		\$781.20	\$ 781.20	bf	\$ 781.20
2	FRONT RH FENDER INNER SHIELD	1		\$200.90	\$ 200.90	?	\$ 200.90
3	FRONT RH FENDER INNER SHIELD CLIPS	10		\$5.00	\$ 50.00	?	\$ 50.00
4	FRONT RH FENDER VVTI	1		\$50.00	\$ 50.00	new	\$ 50.00
5	FRONT RH SPORT RIM	1		\$1,645.10	\$ 1,645.10	cut	\$ 1,645.10
6	FRONT RH DOOR	1		\$1,079.60	\$ 1,079.60	btv	\$ 1,079.60
7	FRONT RH DOOR HINGES	2		\$85.00	\$ 170.00	Ry	\$ 170.00
8	REAR RH DOOR	1		\$1,079.60	\$ 1,079.60	Rx	\$ 1,079.60
9	REAR RH DOOR HINGES	2		\$85.00	\$ 170.00	x	\$ 170.00

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
10	FRONT RH DOOR OUTER MOUNDING	1		\$155.20	\$ 155.20	X	\$ 155.20
11	FRONT RH DOOR STICKER	1		\$45.00	\$ 45.00	ali	\$ 45.00
12	REAR RH DOOR OUTER MOUNDING	1		\$155.20	\$ 155.20	X	\$ 155.20
13	REAR RH DOOR STICKER	1		\$45.00	\$ 45.00	X	\$ 45.00
14	REAR RH DOOR HINGES	2		\$85.00	\$ 170.00	X	\$ 170.00
				SUBTOTAL	\$ 7,896.80	SUBTOTAL	\$ 7,896.80
				GST 8%	\$ 631.74	GST 8%	\$ 631.74
				TOTAL	\$ 8,528.54	TOTAL	\$ 8,528.54

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

Tanfiah 97445749
WP' 10/1/22 @ 1010am
4/5 Repair after repair
Tanfiah @ 11am - 12pm
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: