



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD  
10 EUNOS ROAD 8  
SINGAPORE POST CENTRE #09-04A  
SINGAPORE 408600

Ref: CS/ICS23000261/Kqy3

Date: 09/01/2023

Code: ICS

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 4003M	Veh. Inspected	SMP 9535B
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC2300001H/ST	Excess (\$)	0.00
Assign From	SHARON LIM	Assign Date	09/01/2023

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	03/01/2023	Inspection Date
Survey held at	TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722	

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--