

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305539459
Date : 24.12.2022

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SH 9787L

Date of Accident : 10.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- SMS9843X

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (include advertisement stickers etc,if any)

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

\$550.00

\$550.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : LIM T S

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : NAZ

Name : NAZ

Date : 9/1/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

SAS-KIV

DATE: 12.12.2022

LKK - Naz

MODEL: Hyundai Ioniq

INSURANCE: CHINA TAIPING (45)

VEHICLE NO.: SH 9787L

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper Cover	1		\$ 481.10
	Front Bumper Centre Upper Moulding	1		\$ 368.50
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	Front Bumper Top Brkt LH	1		\$ 35.00
	Front Bumper Side Brkt LH	1		\$ 28.00
	HeadLamp LH	1		\$ 2,110.30
	DayLight LH	1		\$ 642.50
	DayLight Grille LH	1		\$ 93.45
	SUB TOTAL			\$ 3,780.85
	LESS 20%			\$ 756.17
	DISCOUNTED TOTAL			\$ 3,024.68
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Check Lightings			\$ 40.00
	TOTAL LABOUR			\$ 740.00
	ESTIMATE TOTAL			\$ 3,764.68

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Naz LKK
12/12/2022 1606
LCS
2 DAYS
CHECK ITEM PHOTOS
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: