



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|--|------------|
| AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 | | Ref: CS/AGI23000270/Rqy3e2 Date: 17/05/2023 | Code: AGI |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SJC 3893K | Veh. Inspected | JUS 1416 |
| Policy No. | P10229544R03 | Coverage (\$) | 0.00 |
| Claim No. | C10019550/CD | Excess (\$) | 0.00 |
| Assign From | MAYBIE CHUA | Assign Date | 09/01/2023 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | WMOTO RT3 | c.c | 247 |
| Engine No. | HIDDEN | Year of Reg. | 2021 |
| Chassis No. | PRSZRT25BMA000192 | Colour | BLUE |
| Odometer | 24339 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 120/70-15 | TIMSUN | 4 mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | 140/70-14 | TIMSUN | 4 mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 29/12/2022 | Inspection Date | 10/01/2023 |
| Survey held at | KIM KOCK MOTOR PTE LTD BLK 27A JURONG PORT ROAD #01-19 SINGAPORE 619101 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |