

# SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6, #01-73, AUTOBAY, SINGAPORE 4179883

Tel: 96195936 / info@speedwerkz.biz

not Allowed  
for  
9/1/23  
2/5813,000  
10 days.

VEHICLE NUMBER: SJD3076Y  
MAKE & MODEL: HONDA CIVIC  
DOA: 08.1.2023  
CLAIM TYPE: TP CLAIM

## ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BONNET	1	\$967.30	X
FRONT BONNET LOCK	1	\$128.50	X
FRONT BONNET HINGES @48.70	2	\$97.40	X
FRONT BONNET INNER RUBBER	1	\$35.30	X
FRONT BONNET INSULATOR	1	\$104.20	X
FRONT GRILLE EMBLEM TYPE R	1	\$97.60	X
FRONT SUPPORT PANEL	1	\$572.70	474.20
FRONT HEADLAMP @ 1129.40	2	\$2,258.80	X
FRONT HEADLAMP LOWER BRACKET @129.40	2	\$258.80	X
FRONT FENDER @ 625.60	2	\$1,284.60	X
FRONT FENDER DUST COVER @ 112.30	2	\$224.60	X
FRONT BUMPER REINFORCEMENT	1	\$306.30	274.
FRONT BUMPER REINFORCEMENT BRACKET @36.40	2	\$72.80	X
FRONT BUMPER SIDE RETAINER @ 35.50	2	\$71.00	50
FRONT FOG LAMP @ 328.80	2	\$657.60	X
FRONT FOG LAMP COVER @ 48.50	2	\$97.00	X
FRONT HORN	1	\$66.30	X
RADIATOR	1	\$1,593.80	1100.40
RADIATOR FAN MOTOR	1	\$394.90	X
RADIATOR FAN COWLING	1	\$136.70	X
RADIATOR FAN BLADE	1	\$72.90	X
RADIATOR TOP BRACKET @35.20	2	\$70.40	X
AIRCON CONDENSER	1	\$911.40	704.80
AIRCON FAN MOTOR	1	\$476.50	X
AIRCON FAN COWLING	1	\$106.40	X
AIRCON FAN BLADE	1	\$72.90	X
FRONT NUMBER PLATE GARNISH	1	\$66.80	X
REAR BOOT	1	\$865.20	610
REAR BOOT LOCK	1	\$223.70	197
REAR BOOT LOCK CATCH	1	\$36.80	X
REAR BOOT EMBLEM (CIVIC)	1	\$33.50	X
REAR BOOT EMBLEM (1.8)	1	\$28.50	X
REAR BOOT EMBLEM (I-VTEC)	1	\$28.50	X
REAR BOOT CENTRE EMBLEM	1	\$45.20	X
REAR BOOT REFLECTOR LAMP @272.80	2	\$545.60	X
REAR BOOT RUBBER	1	\$195.20	X
REAR BOOT HINGES @\$113.50	2	\$227.00	X
REAR BOOT INNER COVER	1	\$223.70	X
REAR NUMBER PLATE LAMP GARNISH	1	\$134.50	108
REAR NUMBER PLATE LAMP @ 37.00	2	\$74.00	X
REAR TAIL LAMP @455	2	\$910.00	596
REAR TAIL LAMP LOWER BRACKET #34.80	2	\$69.60	30
REAR TAIL LAMP PANEL @176.40	2	\$352.80	X
REAR END PANEL	1	\$659.50	316
REAR END PANEL TOP GARNISH	1	\$188.50	145

8294.9

REAR BUMPER SIDE RETAINER @ 25.30	SELF	2	\$50.60	/
REAR SPARE TYRE PANEL	crumpled/dnc	1	\$1,352.20	998
REAR SPARE TYRE TOP COVER BOARD	unpainted	1	\$391.50	245
REAR SPARE TYRE TOOL TRAY SPONGE	Torn	1	\$256.30	182
REAR SPARE TYRE PANEL TOP INSULATOR	new	1	\$250.00	/
REAR SIDE FLOOR BOARD PANEL @195.30	R	2	\$390.60	X
REAR EXHAUST SILENCER	R	1	\$865.20	X
REAR EXHAUST RUBBER @25.80	11	2	\$51.60	X
REAR WINDSCREEN MOULDING	11	1	\$135.20	X
REAR FENDER @1230.20	R	2	\$2,460.40	X
REAR FENDER INNER GARNISH @367.80	282 x 2 = 282	2	\$735.60	564
REAR FENDER AIR VENT @38.50	11	2	\$77.00	X

\$23,061.50

LESS 20%

\$4,612.30

Sub Total

\$18,449.20

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT AND REAR NUMBER PLATE	1 SET	\$100.00	40
FRONT BUMPER ( MUGEN RACING ) SPORP	1	\$3,500.00	1500
FRONT BUMPER LOWER LIP ( MUGEN RACING ) SPORP	1	\$800.00	X
FRONT BUMPER CLIPS	1 SET	\$50.00	32
REAR BUMPER ( MUGEN RACING ) SPORP	1	\$3,500.00	1500
REAR BOOT SPOILER ( MUGEN RACING )	1	\$1,500.00	500
REAR BOOT INSULATOR CLIPS @5	8	\$40.00	X
REAR BUMPER LOWER SPOILER ( MUGEN RACING )	1	\$1,200.00	X
REAR END PENAL TOP GARNISH CLIPS @5	3	\$15.00	X
REAR END PANEL SEALANT	1	\$80.00	50
REAR WINDSCREEN SEALANT	1	\$100.00	X
REAR REVERSE CAMERA	1	\$650.00	X
REAR BUMPER SENSOR	1 SET	\$450.00	200

\$11,985.00

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$200.00	30
TUFF KOTE		\$200.00	120
TO REMOVE AND REPLACE CUSHION SEAT		\$200.00	80
TO REMOVE AND REFIX REAR WINDSCREEN		\$160.00	11 X
TO REMOVE AND REPLACE EXHAUST PIPE		\$160.00	60
TO REMOVE AND REPLACE REVERSE SENSOR		\$150.00	50
TO REMOVE AND REFIX REAR BOOT LID TOP SPOILER AND REAR BUMPER LOWER LIP		\$250.00	12 X
TO REMOVE AND REPLACE SPARE PARTS AND PENAL BEATING		\$2,500.00	2000
TO SPRAY PAINTING		\$2,200.00	1800
REMOVE & REFIX RADIATOR & REFILL COOLANT		\$150.00	100
REMOVE & REFIX AIRCON CONDENSER & REFILL GAS		\$150.00	

Sub Total

\$6,320.00

Grand Total

\$36,754.20

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-10584.5  
202  
8467.60  
3820