

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 10-Dec-22

INSURANCE: MSIG

MODEL: BMW

VEHICLE NO.: SLV 4517 S

DESCRIPTION	QTY	UNIT PRICE	NETT PRICE
REAR BUMPER <i>1189.75</i>	1	<i>Rs 1M</i>	\$1,384.55 ✓
REAR BUMPER REINFORCEMENT	1		<i>R</i> \$577.45 X
REAR BUMPER LOWER GARNISH	1		<i>R</i> \$189.56 X
REAR BUMPER SENSOR	2	\$285.55	<i>R</i> \$571.10 X
SUB TOTAL			\$2,722.66
LESS 0%			
DISCOUNTED TOTAL			
SUB TOTAL			\$0.00
Labour Charge	1	\$300.00	\$300.00 <i>20H</i>
Panel Beating	1	\$80.00	\$80.00 <i>60L</i>
check rear wing & replace sensor	1	\$400.00	\$400.00 <i>250L</i>
Spray Painting Charge			\$780.00
TOTAL LABOUR			
			\$3,502.66
ESTIMATE TOTAL			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Not Notified
@1635.51
Runny After Rain

L&K Auto Consents to advise notify the Repairer of the following:
 • To reschedule for minor spray painting
 • To display damaged parts during assembly
 • Paint prices are subject to fluctuation



Search



EN
US