

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719

Tel: 6269 9192 H/P: 9631 1712

Business Reg. No: 36463500B

M/s: MS FIRST CAPITAL INSURANCE LTD

36 Robinson Road

#16-01 City House

Singapore 068877

Date : 17.01.2023

Motor Claim Dept

Vehicle number : XD 1796 A

Make/Model : ISUZU CYZ

Date of accident : 03.11.2022

Claim Type : TP Claim

Accident involving XD 1796 A & SHD 6078 X

Re: Estimate

1. 1 PC TAIL LAMP 15%
2. 1 PC TAIL LAMP BRACKET
3. 1 PC REAR MUDGUARD
4. 1 PC REAR MUDFLAT
5. 1 PC REAR MUDGUARD BRACKET
6. 1 PC REAR TYRE

LKK Auto Cons. is the Repairer of the following.
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 385.00 *over*
\$ 600.00 *66*
\$ 800.00 *66*
\$ 50.00 *th*
\$ 230.00 *lt*
\$ 450 600.00 *ab* *80% 360*

ISUZU DISCOUNT -15%

SUB TOTAL

\$ 2,665.00
\$ 399.75
\$ 2,265.25

WIRING SERVICES

LABOUR CHARGES

PUTTY & SPRAY PAINTING

\$ 80.00 *30*
\$ 800.00 *600*
\$ 500.00 *300*

Yours Faithfully,

TOTAL

\$ 3,645.25 *930*

李光華 摩 咭 燒 焊

LEE KUAN HWA MOTOR SERVICE

39, Westwood Avenue, Singapore 648719

TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

Tanphun 97415749/62563581
17/1/23 @ 12pm
L/S Resurvey after repair
tanphun@khamtan.com
3-4 days.