



Borneo Motors

incharge

o. Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
o. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

TOYOTA
Kkk Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Account Details	Account No.	Customer Details
D PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 07/01/2023	Work: 65703925

Car	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
16	ZVW50R	AHXEBW Q2	12/01/2017	SLK2958Z	0	19541	75/DS/SLK2958Z

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
DKB3FU603542880	2ZRR987591	60	Ng Mei Yen	--/--/----	0.00 --/--/----

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: SLL7343J ACC DATE: 06/01/23 TOW IN: 06/01/23 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30 100.00
B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				198.00
B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
B	BP-LAB2 R/I FRONT RIGHT DOOR COMPARTMENT				792.00
B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				792.00
B	BP-RES2 RESPRAY ACC AFF AREA				854 3836.00
1	U68101-47230 GLASS SUB-ASSY, FR <i>504 830.45</i>	1.00	977.00		977.00
2	U67401-47010 FRAME SUB-ASSY, FR <i>504 147.30</i>	1.00	173.30		173.30
3	U68125-47030 GLASS, FR DOOR FIX <i>MU 326.31</i>	1.00	383.90		383.90
4	U87910-47450 MIRROR ASSY, OUTER <i>CA 1468.54</i>	1.00	1727.70		1727.70
5	U87915-47070 B0 COVER, OUTER MIRROR, <i>MIS 111.09</i>	1.00	130.70		130.70

on behalf of	Customer's Signature	Charge Summary	Total
o Motors (Singapore) Pte Ltd			10,992.60
	Please acknowledge receipt of vehicle	Parts 3,392.60	GST 8.00% 879.41
		Labour 7,600.00	
		Sublet 0.00	
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 11,872.01



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1168



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details			
Income Insurance Limited 5 Bras Basah Road Singapore 189557 Attention: Motor Claims Dept		S1000009 / ICN11		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
		Document No.					
		0					
		Document Date					
		07/03/2023					

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q2	12/01/2017	SLK2958Z	0	19541	75/DS/SLK2958Z

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU603542880	2ZRR987591	60	Ng Mei Yen	10/01/2023 8.00	20/01/2023 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SLL7343J ACC DATE:06/01/23 TOW IN:06/01/23 DATE-IN: DATE SURVEY:10/01/23 NO OF REPAIR DAYS:3 DAY BY:RASUL LKK				30.00
2	S	BP-SUBLET CHECK WIRING AND CONDUCT LEAK TEST	0742			198.00
3	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			198.00
4	S	BP-SUBLET REPL ACC AFF AREA	0742			792.00
		STRAIGHTEN AND PANEL BEAT ACC AFF AREA				
5	S	BP-SUBLET RESPRAY ACC AFF AREA	0742			854.00
6	1	U68101-47230 GLASS SUB-ASSY, FR	1.00	977.00	15.00	830.45
7	2	U68125-47030 GLASS, FR DOOR FIX	1.00	383.90	15.00	326.31
8	3	U87910-47450 MIRROR ASSY, OUTER	1.00	1727.70	15.00	1468.54
9	4	U87915-47070 B1 COVER, OUTER MIRROR,	1.00	130.70	15.00	111.09
10	5	U67401-47010 FRAME SUB-ASSY, FR	1.00	173.30	15.00	147.30
11	6	U68141-47061 RUN, FR DOOR GLASS,	1.00	174.70	15.00	148.49

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			5,104.18
	Please acknowledge receipt of vehicle	Parts 3,032.18	GST 8.00% 408.33
		Labour 30.00	
		Sublet 2,042.00	
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 5,512.51

Customer Copy