

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGW 8335 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00 X nh	
3	TO CARRY OUT DE-ENERGISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACIVATION.	S/N \$ 480.00 ✓	
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00 600	
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,500.00 650	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,802.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 8335 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,896.00	OK Cna / 2316.80
2	FRONT BUMPER TRIM - LH / RH	2	\$ 130.00	X
3	FRONT BUMPER FIXING PARTS	1	\$ 658.00	X } Cna
4	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 248.00	OK Cna / 198.40
5	FRONT BUMPER FOAM PART - LH	1	\$ 34.00	X } Cna
6	FRONT BUMPER SUPPPORT COVER - LH / RH	2	\$ 78.00	X } Cna
7	FROTN BUMPER FOAM PART - UPPER	1	\$ 150.00	OK Cna / 120.00
8	FRONT BUMPER FOAM PART - LOWER	1	\$ 125.00	X } Cna
9	FRONT BUMPER PLASTIC FOAM STRIP	1	\$ 134.00	X } Cna
10	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 283.00	OK Cna / 226.40
11	FRONT BUMPER GRILLE - CENTER	1	\$ 171.00	OK Cna / 136.40
12	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 235.00	X
13	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 202.00	X
14	FRONT BUMPER IMPACT PROTECTION	1	\$ 899.00	X
15	FRONT BUMPER SPOILER - LH / RH	2	\$ 220.00	X
16	FRONT BUMPER AIR GUIDE - LH / RH OUTER	2	\$ 116.00	X
17	FRONT BUMPER AIR GUIDE - LH / RH INNER	2	\$ 90.00	X
18	RADIATOR AIR GUIDE - LH / RH	2	\$ 268.00	X
19	RADIATOR GRILLE	1	\$ 2,317.00	Cna / 1853.60
20	RADIATOR GRILLE COVER CAP	1	\$ 141.00	OK Cna
SUB TOTAL SPARE PARTS		:	\$ 9,395.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 8335 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR GRILLE BRACKET	1	\$ 104.00 X	} 233.20 cm ✓
22	RADIATOR GRILLE COVER	1	\$ 69.00 X	
23	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 246.00 X	
24	RADIATOR GRILLE COVER - LH / RH	2	\$ 122.00 X	
25	FRONT "360" CAMERA	1	\$ 1,006.00 X	
26	FRONT BUMPER WIRING SET	1	\$ 642.00 X	
27	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,451.00 X	
28	FRONT BUMPER SUPPORT BRACKET	1	\$ 481.00 X	
29	FRONT BUMPER BRACKET - LH / RH	2	\$ 174.00 X	
30	FRONT BUMPER SIGHT SHIELD	1	\$ 118.00 X	
31	FRONT BUMPER SIGHT SHIELD	1	\$ 119.00 X	
32	FRONT BUMPER GUIDE SECTION - LH	1	\$ 50.00 X	
33	CAUTION LABEL	1	\$ 23.00 X	
34	FRONT PARKING AID SENSOR - INNER	1	\$ 584.00 X	} 233.20 cm ✓
35	FRONT PARKING AID SENSOR - OUTER	1	\$ 292.00	
36	FRONT PARKING AID SEAL RING	4	\$ 10.00 X	} ?
37	FRONT SPOILER - LH / RH	2	\$ 212.00 X	
38	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 598.00 X	
39	RADIATOR AIR GUIDE BRAKE - LH / RH	2	\$ 100.00 X	
40	FRONT FENDER - LH	1	\$ 2,477.00	
SUB TOTAL SPARE PARTS		:	\$ 8,878.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 8335 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER BRACKET - LH	1	\$ 11.00	X
42	FRONT FENDER BRACKET - CENTRE LH	1	\$ 15.00	X
43	FRONT FENDER BRACKET - REAR	1	\$ 15.00	X
44	FRONT FENDER BRACKET - LH	1	\$ 76.00	X
45	FRONT FENDER BRACKET - LH INNER	1	\$ 18.00	X
46	HEADLIGHT SEAL - LH	1	\$ 60.00	?
47	FRONT SUPPORT ELEMENT - LH	1	\$ 45.00	?
48	HEADLIGHT - LH	1	\$ 8,660.00	?
49	FRONT WHEEL COVER - LH / RH	2	\$ 648.00	Cost ✓
50	LIFT CYLINDER - LH / RH	2	\$ 518.00	X WH
51	LIFT CYLINDER HOSE	1	\$ 111.00	X WH
52	FRONT NO PLATE	S/N	\$ 60.00	bt 60.00
53	SUNDRIES		\$ 500.00	✓ net 14.48
TOTAL SPARE PARTS		:	\$ 29,010.00	
TOTAL LABOUR CHARGES		:	\$ 6,802.00	
GRAND TOTAL		:	\$ 35,812.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanpin 97495749
Not Authorised Ex: 164
03 days 6/1/73 C245
Resurvey before paint
Tanpin C11hantow

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0007/2023/EQ

16-Feb-23

CHANG

1 of 1

SGW 8335 C

AUDI E-TRON

Quantity	Description	Unit Price	Amount
Parts			
1	LICENCE PLATE HOLDER <i>cm</i>	\$ 229.00	182.80
2	RADIATOR AIR GUIDE - UPPER <i>cm</i>	\$ 89.00	70.80
GRAND TOTAL			\$ 318.00

For Premium Automobiles Pte Ltd

Rose
16/02/23



Authorised Signature