# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01

Singapore 068897

From: LKK Auto Consultants Pte Ltd

Est. Duration of Repair

: 9

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 11 Jan 2023

## **Preliminary Advice**

 Vehicle No
 : SMW1455P
 Accident Date
 : 01/01/2023

 Make
 : RENAULT SCENIC IV
 Policy No.
 : SP2002451400

 Assignment Date
 : 10/01/2023
 Excess
 : \$\$2,000.00

Date of Inspection : 11/01/2023

Inspection At : MUNICH AUTOCARE PTE LTD (HQ)

60 JALAN LAM HUAT, #07-43

SINGAPORE 737869

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,756.76
Revised Amount	:S\$	17,202.76
Check Items (Estimated)	:S\$	11,770.16
Total	:S\$	28,972.92

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 116,000.00

 COE / PARF Rebate
 :S\$ 41,121.00

Salvage Value :S\$

Margin for Repair :S\$ 74,879.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kir	ndly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.