



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD
10 EUNOS ROAD 8
SINGAPORE POST CENTRE #09-04A
SINGAPORE 408600

Ref: CS/ICS23000353/Tvy3

Date: 11/01/2023

Code: ICS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJT 7679Y
Policy No. MPC22A00072301	Coverage (\$)	0.00
Claim No. DMPC2300023H/ST	Excess (\$)	4,250.00
Assign From SHARON TAN	Assign Date	11/01/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/01/2023	Inspection Date	11/01/2023
Survey held at	39 Woodlands Close #01-12, Mega@Woodlands,		
Repairer	YEW TEE AUTOMOBILE TECH PL		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.