



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23000355/Uvy3m4 Date: 23/05/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 5733B	Veh. Inspected	FBU 150R	
Policy No.	SI22V15852/VCV/R02	Coverage (\$)	0.00	
Claim No.	IVS23/0079	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	11/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA NMAX	c.c	155	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	MH3SG5680NK133571	Colour	BLACK	
Odometer	9997 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110-70-13	IRC	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80-70-13	IRC	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2022	Inspection Date	11/01/2023	
Survey held at	SANFU MOTOR PL 1 KAKI BUKIT AVENUE 6 #02-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)REGISTRATION DATE: 22 JUL 2022 C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	