



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23000356/Tvy3e2 Date: 06/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMH 7244X	Veh. Inspected	SLA 3059P	
Policy No.		Coverage (\$)	0.00	
Claim No.	BVS23/0019	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	11/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN TIGUAN 1.4 TSI	c.c	1390	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WVGZZZ5NZGW065774	Colour	BLACK	
Odometer	70383 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/45 R18	GOODYEAR	5 mm	
L/H Front Tyre	255/45 R18	GOODYEAR	5 mm	
R/H Rear Tyre	255/45 R18	GOODYEAR	6 mm	
L/H Rear Tyre	255/45 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2022	Inspection Date	11/01/2023	
Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-59 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)REGISTRATION DATE: 26 FEB 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	