

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	Ref:	CS/AGI23000361/y3	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		ate:	11/01/2023	
4		Delieu Deutieuleus		ode:		
1.						
	Insured Veh.	SMK 4646Z	Veh. Inspected		SLV 1047B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10019759 /JT	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		11/01/2023	
2.	Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	09/01/2023	Inspection Date			
	Survey held at	CARSMITH PTE LTD				
		BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807				
5a.	Remarks					

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.