

INSURANCE CO.: ALLIED WORLD

Supplementary Parts For Registration No.: SMW 7108 C

<u>Parts</u>		<u>Cost (\$)</u>
1	Headlight assy LH <i>scm</i>	1,063.00
2	Bumper Bracket <i>scm</i>	265.00
3	Bumper bracket <i>scm</i>	491.00
4	Tailgate <i>scm</i>	2,988.00
5	Badge <i>scm</i>	91.00
6	Badge <i>scm</i>	114.00
Total Parts		5,012.00

<u>Labour</u>		<u>Cost (\$)</u>
1	Remove & reinstall rear windscreen glass and conduct water leak test	380.00 ✓
2	Supply rear windscreen glass sealant	80.00 ✓
3	Replace tailgate	760.00 ✓
4	Respray tailgate	550.00 ✓
Total Labour		1,770.00

Taxable amount	6,782.00
8% GST	542.56
Grand total	\$ 7,324.56

Thank You.

Yours faithfully

[Signature]
 LOI AI TING
 Senior Officer - Admin
CITROEN SERVICE CENTRE
 DID : 6568 4556 / 6568 4501
 FAX : 6567 5258 / 6565 1240