



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM23000376/Rvp3	
	8 SHENTON WAY AXA TOWERSING			Date:	11/01/2023	
				Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 4701D	Veh. Inspected	t	FBT 1609J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S3M04HDM	Excess (\$)		0.00	
	Assign From	KHOR SAW THENG	Assign Date		09/01/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	. General Information					
	Accident Date	31/12/2022	Inspection Dat	te	11/01/2023	
	Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE				
		50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING				
5a.		SINGAPORE 659578	marke			
oa.	Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.					
	B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					