

COMFORTDELGRO ENGINEERING

TAXI/01/23/2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305542345
Date : 11.01.23
Time of Fax :

Via Fax : # 63687421
Your Insured : SHB 817B
Date of Acc : 11.01.23

Attn: Motor Claims Department

STRIDES

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D 32294

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
♦ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
♦ <u>Chiang Liat Cheon</u>	Tel: <u>6214 8314</u> or HP: <u>9296 6006</u>

} **chianglc@cdge.com.sg**
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully


For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD**REPAIR ESTIMATE***

VEHICLE NO SHD3229Y

DATE 11.01.2013

MAKE REG 30.06.2016

CHIANG /STRIDES

MODEL HYU- I40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT FENDER RH			\$663.00
1	FRONT FENDER SHIELD RH			\$174.90
1	HEAD LAMP RH			\$1,388.00
1	HEADLAMP SUPPORT PANEL			\$907.40
1	FRONT BUMPER			\$1,052.20
1	FRONT BUMPER SIDE BRACKET /RH			\$49.20
1	FRONT BUMPER GRILLE RH			\$187.20
	SUB TOTAL			\$4,421.90
	20.00%			\$884.38
	DISCOUNTED TOTAL			\$3,537.52
	Labour Charge			
	Panel Beating			\$560.00
	Spray Painting Charge			\$600.00
	Check wiring			\$60.00
	Tuff kote			\$60.00
	TOTAL LABOUR			\$1,280.00
	ESTIMATE TOTAL			\$4,817.52
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				