# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Attn:

Singapore 079120

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Noor Amran, Noor Yussyuhaila Date: 05 Jun 2023

## **Preliminary Advice**

 Vehicle No
 : SDB5957Z
 Accident Date
 : 07/01/2023

 Make
 : AUDI A8 L
 Policy No.
 : 1800152122

 Assignment Date
 : 13/01/2023
 Excess
 : \$\$700.00

Date of Inspection : 11/01/2023 Est. Duration of Repair : 6

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	54,519.16 (Estimate \$51,755.00 + Supplementary \$2,764.16)
Revised Amount	:S\$	34,410.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	34,410.08
Lump Sum Repair	:S\$	

#### **Total Loss Consideration**

:S\$	
:S\$	240,000.00
:S\$	98,633.00
	:S\$

Salvage Value :S\$

Margin for Repair :S\$ 141,367.00

#### Remarks

(	X	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(		)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(	Χ	)	Other comments : KINDLY APPROVE ON SUPPLEMENTARY.