SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622 Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

DATE: 16/02/2023

Invoice No: SG98-23-012

LONPAC INSURANCE BHD 300 Beach Road #17-04/06 The Concourse Singapore 199555

Claim Ref:

22/23/23/VC0/026829

Attn:

Your Insured:

GBE 6874E

Date of Accident:

10/1/2023

Location:

Grange Road

FINAL REPAIR COSTS

VEHICLE NO.

FY 5077T

Honda CB 400

Cost of Repair for Vehicle No.:

FY 5077T (Lump Sum)

\$1,600.00

Total:

\$1,600.00

SINGAPORE DOLLARS: ONE THOUSAND SIX HUNDRED ONLY

Notes:

- 1. All cheque payment should be "Crossed" and made payable to SG98 MOTOR PTE LTD
- 2. All cheque should have our "Invoice No" written on the reverse side of the cheque
- 3. For further enquiries on this invoice, please feel free to contact us

SG98 MOTOR PTE LTD

:LG

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622 Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

DATE: 16/02/2023

LONPAC INSURANCE BHD

LETTER OF DEMAND

300 Beach Road

#17-04/06 The Concourse

Singapore 199555

Claim Ref:

22/23/23/VC0/026829

Attn:

Your Insured:

GBE 6874E

Date of Accident:

10/1/2023

Location:

Grange Road

FINAL REPAIR COSTS

VEHICLE NO. FY 5077T

Honda CB 400

Cost of Repair for Vehicle No.:

FY 5077T (Lump Sum)

\$1,600.00

Loss of Use

3 Days X \$30

\$90.00

.

Total:

\$1,690.00

SINGAPORE DOLLARS: ONE THOUSAND SIX HUNDRED AND NINETY ONLY

Notes:

- 1. All cheque payment should be "Crossed" and made payable to SG98 MOTOR PTE LTD
- 2. All cheque should have our "Invoice No" written on the reverse side of the cheque
- 3. For further enquiries on this invoice, please feel free to contact us

SG98 MOTOR PTE LTD

:LG