

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 02 Feb 2023

Preliminary Advice

Vehicle No	: SMS7605E	Accident Date	: 06/01/2023
Make	: AUDI A4	Policy No.	:
Assignment Date	: 13/01/2023	Excess	: S\$550.00
Date of Inspection	: 12/01/2023	Est. Duration of Repair	: 6
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	41,338.00	(Estimate \$38,758.00 + Supplementary \$2,580.00)
Revised Amount	:S\$	22,980.00	
Check Items (Estimated)	:S\$	484.00	
Total	:S\$	23,464.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	230,000.00
COE / PARF Rebate	:S\$	133,440.00
Salvage Value	:S\$	
Margin for Repair	:S\$	96,560.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.