

SPEEDWERKZ PRIVATE LIMITED
 1 Kaki Bukit Avenue 6 #01-73, AUTOBAY, Singapore 417883
 Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SFJ7882B
 MAKE & MODEL: TOYOTA HARRIER
 DOA: 14/1/2023
 CLAIM TYPE: OD CLAIM

*not Authorized
 her
 words
 16/1/23
 1/5 @ 17,000
 through After repair
 excess \$1000
 10 days.*

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER	1	\$1,018.13	✓ 800
FRONT BUMPER AIR GRILLE	1	\$746.39	X
FRONT BUMPER REINFORCEMENT	1	\$443.45	X
FRONT BUMPER SIDE RETAINERS @115.20	2	\$195.84	X 60
FRONT BUMPER FOG LAMP @115.20	2	\$438.60	X 260
FRONT BUMPER CENTRE SPONGE	1	\$146.20	X
FRONT BUMPER TOW COVER @78.60	2	\$133.62	X
FRONT BUMPER PARKING SENSOR @481.90	2	\$819.23	X
FRONT BUMPER CENTER PARKING SENSOR HOLDER @78.00	2	\$132.60	X
FRONT BUMPER CORNER SPONGE @49.80	2	\$84.66	X
FRONT RADAR SENSOR	1	\$2,102.05	X
FRONT WIPER GRILLE	1	\$746.39	X
FRONT WIPER GRILLE CORNER GARNISH @47.60	2	\$80.92	X
FRONT BONNET	1	\$1,685.55	X
FRONT BONNET LOCK	1	\$139.91	X
FRONT BONNET INSULATOR	1	\$652.29	X
FRONT BONNET ABSORBER HOLDER @475-	2	\$807.50	X
FRONT BONNET HINGES @87.10	2	\$148.07	X
FRONT GRILLE ASSY	1	\$1,148.69	X
FRONT BONNET CHROME MOULDING	1	\$395.76	X
FRONT SUPPORT PANEL	1	\$951.15	X
FRONT SUPPORT PANEL TOP GARNISH	1	\$340.17	X
FRONT HEADLAMP @772.50 RH	1	\$5,756.97	X 3100
FRONT FENDER @115.20 RH	1	\$1,231.06	X 680
FRONT FENDER INNER SHIELD @115.20 RH	1	\$443.70	X 220
FRONT FENDER TOP SEAL @85.40 RH	1	\$72.59	X
FRONT FENDER TOP QUARTER GARNISH @75 RH	1	\$63.75	X
FRONT BUMPER CENTRE TOP BEAM	1	\$265.20	X
FRONT BUMPER SIDE TOP BEAM RH	1	\$90.10	X
RADIATOR ASSY	1	\$2,239.24	X
RADIATOR TOP HOSE	1	\$62.39	X
RADIATOR BOTTOM HOSE	1	\$77.27	X
RADIATOR FAN MOTOR	1	\$476.09	X
RADIATOR FAN COWLING	1	\$301.84	X
RADIATOR FAN BLADE	1	\$215.22	X
RADIATOR TOP PLATE	1	\$209.95	X
RADIATOR SIDE GARNISH @85	2	\$144.50	X
AIR CON CONDENSER	1	\$1,737.49	X
AIRCON FAN MOTOR	1	\$476.09	X
AIRCON FAN COWLING	1	\$301.84	X
AIRCON FAN BLADE	1	\$215.22	X
HORN @148	2	\$251.60	X
AIR CON CONDENSER SIDE GARNISH @85	2	\$144.50	X
RADIATOR SPARE TANK	1	\$424.75	X
WIPER WASHER TANK	1	\$129.88	X
WIPER WASHER TANK MOTOR @295.10	2	\$501.67	X
AIRCON LIQUID PIPE	1	\$404.69	X
AIRCON SUCTION HOSE	1	\$423.47	X
AIRCON DISCHARGE HOSE	1	\$626.71	X

AIRCON LIGHT PRESSUER HOSE	11	1	\$1,091.40	X	
FRONT DOOR CHROME MOULDING	11	1	\$243.10	X	
FRONT DOOR HINGES @75 RH	11	2	\$127.50	X	
FRONT DOOR RH	R	1	\$1,633.96	X	
FRONT DOOR GLASS REGULATOR MOTOR RH	11	1	\$735.00	X	
FRONT DOOR RUBBER RH	11	1	\$312.21	X	
FRONT DOOR LOWER GARNISH RH	11	1	\$329.80	X	
FRONT WHEEL BEARING RH	Day	1	\$667.25	X	450
FRONT LOWER ARM RH	Ant	1	\$622.20	X	480
FRONT SHOCK ABSORBER	Ant	1	\$545.87	X	380
REAR DOOR CHROME MOULDING	11	1	\$250.75	X	
REAR DOOR LH	R	1	\$1,460.30	X	
REAR FENDER ARCH GARNISH	11	1	\$350.80	X	
ROCKER PENAL MOULDING	11	1	\$290.96	X	
REAR SHOCK ABSORBER LH	Ant	1	\$460.02	X	380
REAR CONTROL ARM LH	Ant	1	\$354.62	X	300
REAR KNUCKLE ARM LH	Ant	1	\$607.92	X	520
REAR LOWER ARM LH	Ant	1	\$538.31	X	400
REAR HUB BEARING LH	Ant	1	\$294.95	X	
REAR BOOT LID	20/ant	1	\$2,175.32	X	1200
REAR BOOT LID LOCK	11	1	\$590.92	X	
REAR BOOT LID LOCK CATCH	11	1	\$166.60	X	
REAR BOOT LID ABSORBER HOLDER (AUTO) 786.50	11	2	\$1,337.05	X	
REAR BOOT LID HINGES @136.30	11	2	\$231.71	X	
REAR BOOT RUBBER	11	1	\$288.66	X	
REAR BOOT INSULATOR	11	1	\$474.98	X	
REAR TURBO EMBLEM	11	1	\$64.01	X	
REAR BOOT LID CENTRE GARNISH	11	1	\$501.08	X	
REAR BOOT LID EMBLEM (HARRIER)	11	1	\$75.14	X	50
REAR BOOT LID REFLECTOR LAMP @499.60	11	2	\$764.32	X	
REAR BOOT LID SIDE AUTO GATE SENSOR @422	11	2	\$717.40	X	
REAR END PANEL	20/ant	1	\$803.51	X	600
REAR END PANEL TOP GARNISH	11	1	\$304.73	X	
REAR FLOOR PANEL	R	1	\$1,786.87	X	
REAR TAIL LAMP @1233.80	8/511	2	\$2,097.46	X	1PC 860
REAR FENDER INNER GARNISH @1000 NIS	NIS	1	\$780.39	X	380
REAR BUMPER	D.H.	1	\$1,237.77	X	800
REAR BUMPER SIDE RETAINER @121.90	one/ant	2	\$207.23	X	120
REAR BUMPER REINFORCEMENT	N.F.	2	\$701.42	X	
REAR BUMPER SENSOR @225	M.I.	4	\$765.00	X	
REAR BUMPER SENSOR HOLDER @25	M.I.	4	\$85.00	X	
REAR BUMPER INNER SPONGE	M.I.	1	\$140.42	X	100
REAR BUMPER DIFFUSER	M.I. NN	1	\$551.23	X	
REAR BUMPER REFLECTOR @76.30	M.I.	2	\$529.71	X	100
REAR BUMPER LOWER COVER q.r vent 1(1)	1000	1	\$177.65	X	140
REAR EXHAUST SILENCER	11	1	\$846.86	X	
REAR EXHAUST RUBBER @45	11	2	\$76.50	X	
REAR EXHAUST CENTRE PIPE	11	1	\$860.37	X	
REAR FENDER @1000 NIS	NIS	1	\$1,593.75	X	1100
REAR FLOOR PANEL TOP COVER	11	1	\$294.95	X	
REAR FENDER INNER PANEL @1680	3000	1	\$1,428.00	X	1000

ADD 10 %
Sub Total

\$63,817.75
\$6,381.77
\$70,199.52

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR SPORT RIM 8 Front Sport R.M.	1	\$2,200.00	8025/N
REAR TYRE	1	\$850.00	X
REAR NUMBER PLATE	11	\$45.00	X
REAR BOOT INSULATOR CLIPS @7	11	\$45.00	X
REAR END PANEL TOP GARNISH CLIPS @7	8	\$56.00	X
REAR FENDER INNER GARNISH CLIPS @7	20	\$140.00	X
TAILGATE WINDSCREEN SEALANT	1	\$100.00	40

REAR END PANEL SEALANT	11	1	\$1,000.00	X
FRONT NUMBER PLATE	11	1	\$45.00	X
FRONT SUPPORT PANEL TOP GARNISH CLIPS	11	1 SET	\$45.00	X
Sub Total			\$4,526.00	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING AND DIAGNOSTIC		\$550.00	30
REMOVE AND REPLACE WINDSCREEN		\$120.00	✓
REMOVE AND REFIX EXHAUST PIPE	11	\$160.00	X
REMOVE AND REFIX UPHOLTERY		\$160.00	60
REMOVE AND REPLACE REVERSE SENSOR		\$160.00	40
REMOVE AND REFIX RADIATOR	11	\$120.00	X
REMOVE AND REFIX AIRCON CONDENSER & REFILL GAS	11	\$150.00	X
LABOUR CHARGE FOR KNOCK DENT AND RENEW PARTS		\$3,500.00	1800
TO SPRAY PAINTING		\$2,500.00	1800
Sub Total			\$7,420.00

Grand Total \$82,145.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-15614.95
 102
 17176.44
 840
 3820
 21866.44
 212
 17653