

Section A - Accident Details

Registration Number	SHB1717D
Case Reference Number	TAX/01/23/2023
Registration Date	30/Nov/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	YEI KIM SENG
Type of Accident	Head to Rear
Accident Date and Time	11/Jan/2023 7:15 PM
Accident Reported Date and Time	12/Jan/2023 12:10 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117422
Special Instruction to ARC, if any	TP/ REAR PORTION/ INCOME - LKK
Prepared Date and Time	12/Jan/2023 1:32 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,200.00	\$800.00
Total Spray Cost	\$1,086.00	\$440.00
Total Spare Part Cost	\$7,338.06	\$2,914.68
Total Other Cost	\$1,590.00	\$540.00
TOTAL COST	\$11,214.06	\$4,694.68 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	5.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / INCOME
ARC / Surveyor Sign Off Date	17/01/2023 11:44 AM	13/01/2023 3:36 PM
Signature		
Remarks	part by part repair / before PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR HP 9749 5749 taufikh@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2302-0042	Invoice Number	
Quotation Date	06.02.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,200.00	\$800.00
Total Labour	\$1,200.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$428.00	\$220.00
TO RESPRAY REAR PANEL	\$230.00	\$0.00
TO RESPRAY TAIL GATE	\$428.00	\$220.00
Total Spray Painting & Panel Beating	\$1,086.00	\$440.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$350.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$120.00	\$120.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00
ISOLATED OF (EV) (NET)	\$150.00	\$150.00
Total Other Costs	\$1,590.00	\$540.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10387827	CAP-R/WDO WPR ARM FIN	1.00	\$6.14	10.00	\$5.53	Replace	Replace
		10376550-WSD	SENSOR-RR PARK DIST CONT	0.00	\$65.00	0.00	\$0.00	Replace	Check
		10726676	LAMP ASM-RR FOG - LH	0.00	\$36.30	0.00	\$0.00	Replace	Check
		10726677	LAMP ASM-RR FOG - RH	0.00	\$189.07	0.00	\$0.00	Replace	Check
		10587412	LAMP ASM-TAIL(LID SI) - RH	0.00	\$407.68	0.00	\$0.00	Replace	Check
		10587411	LAMP ASM-TAIL(LID SI) - LH	0.00	\$407.68	0.00	\$0.00	Replace	Check
		10587410	LAMP ASM-TAIL(BODY SI) - RH	0.00	\$764.09	0.00	\$0.00	Replace	Check
		10587409	LAMP ASM-TAIL(BODY SI) - LH	0.00	\$764.09	0.00	\$0.00	Replace	Check

✓
X
X
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 20/02/2023

User ID : PohSuan

		10327894	BAR ASM-RR BPR IMP	0.00	\$339.77	0.00	\$0.00	Replace	Check	X
		10449047	BRACKET-RR BPR FASCIA LWR MTG - LH	0.00	\$12.80	0.00	\$0.00	Replace	Check	X
		10449056	BRACKET-RR BPR FASCIA LWR MTG - RH	0.00	\$12.80	0.00	\$0.00	Replace	Check	X
		10326369	BRACKET-RR BPR FASCIA SI MTG - LH	0.00	\$46.08	0.00	\$0.00	Replace	Check	X
		10326371	BRACKET-RR BPR FASCIA SI MTG - RH	0.00	\$46.08	0.00	\$0.00	Replace	Check	X
		10465723	BRACKET ASM-RR BPR FASCIA SI-L	0.00	\$29.85	0.00	\$0.00	Replace	Check	X
		10465727	BRACKET ASM-RR BPR FASCIA SI-RH	0.00	\$29.85	0.00	\$0.00	Replace	Check	X
		10359002	FINISHER-RR BPR - LH	1.00	\$47.42	100.00	\$0.00	Replace	Repair	R
		10359003	FINISHER-RR BPR - RH	1.00	\$47.42	100.00	\$0.00	Replace	Repair	R
		10751490	FASCIA-RR BPR LWR	1.00	\$230.68	10.00	\$207.61	Replace	Replace	√
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	10.00	\$682.63	Replace	Replace	√
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	√
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	√
		10896035	EMBLEM ASM-L/GATE (SW EV)	1.00	\$33.90	10.00	\$30.51	Replace	Replace	√
		10885560	EMBLEM ASM-L/GATE (MG5 SW)	1.00	\$21.84	10.00	\$19.66	Replace	Replace	√
		10935050	EMBLEM ASM-RR LIC PLT (MG)	1.00	\$62.92	10.00	\$56.63	Replace	Replace	√
		10562676	PLATE ASM-RR LIC PLT	0.00	\$96.40	0.00	\$0.00	Replace	Check	X
		10395721-SEPP	PANEL ASM-RR END	0.00	\$708.66	0.00	\$0.00	Replace	Check	X
			SEALANT W/SCREEN	2.00	\$37.00	0.00	\$74.00	Replace	Replace	√
		10964627	WINDOW ASM-REAR (WINDSCREEN REAR)	0.00	\$323.44	0.00	\$0.00	Replace	Check	X
		10022051	SWITCH-L/GATE OPEN	0.00	\$30.68	0.00	\$0.00	Replace	Not Given	X
		10314527	LATCH ASM-L/GATE	0.00	\$139.36	0.00	\$0.00	Replace	Check	X
		10321485	WEATHERSTRIP-L/GATE	0.00	\$73.53	0.00	\$0.00	Replace	Check	X
		10444798	STRUT ASM-L/GATE -RH	0.00	\$52.52	0.00	\$0.00	Replace	Not Given	X
		10444797	STRUT ASM-L/GATE - LH	0.00	\$52.52	0.00	\$0.00	Replace	Not Given	X
		10103178	HINGE ASM-L/GATE - RH	0.00	\$30.89	0.00	\$0.00	Replace	Not Given	X
		10103179	HINGE ASM-L/GATE - LH	0.00	\$30.89	0.00	\$0.00	Replace	Not Given	X
		10328219-SEPP	TAIL GATE ASM-LIFT	1.00	\$1,928.26	10.00	\$1,735.43	Replace	Replace	√
Total					\$7,924.09		\$2,872.00			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		10359002	FINISHER-RR BPR - LH	1.00	\$47.42	10.00	\$42.68	Replace	Replace	√
Total					47.42		42.68			

2,914.68
+ 800.00
+ 980.00

4,694.68