



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CS/CTI23000513/p3

Date: 16/01/2023

Code: CTI

**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SLM 5660B	<b>Veh. Inspected</b>	SNJ 1110R
<b>Policy No.</b>	DMPCSNA00228582201	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM23D200268/C02	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	TAN KAH LEONG	<b>Assign Date</b>	16/01/2023

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

**4. Description of Damages**

--

**5. General Information**

<b>Accident Date</b>	09/01/2023	<b>Inspection Date</b>	
<b>Survey held at</b>	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--