

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

DATE : 30.01.2023

VEHICLE NO : **SKS3692C**
MODEL : **TOYOTA ESTIMA**
CHASSIS : **ACR500187557**
DATE OF ACCIDENT : 13.01.2023
DATE OF REG : 10.04.2015

TP 1st Cap.
Hui Roy

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR SIDE MIRROR RH <i>Right</i>	1	\$ 1,450.00	\$ 1,450.00 <i>981</i>
2	FRONT DOOR RH <i>2</i>	1	\$ 1,510.00	\$ 1,510.00 <i>+</i>
3	FRONT DOOR LOWER GUARD RH <i>pl</i>	1	\$ 210.00	\$ 210.00 <i>+</i>
4	FRONT DOOR OUTER STRIP RH <i>for</i>	1	\$ 195.00	\$ 195.00 <i>+</i>
5	FRONT DOOR STICKER RH (BLACK) (SET) <i>He</i>	1	\$ 190.00	\$ 190.00 <i>+</i>

TOTAL PRICE \$ 3,555.00

LESS 25% \$ 888.75

SUB TOTAL PRICE \$ 2,666.25

981
735.75

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR LOWER GUARD RH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00 <i>+</i>

TOTAL \$ 40.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 400.00	<i>100</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 400.00	<i>100</i>
3	TUFF COAT	\$ 150.00	<i>+</i>
4	WIRING CHECK	\$ 100.00	<i>+</i>
5	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	<i>+</i>

200

TOTAL

\$1,130.00

TOTAL PARTS COST : \$ 2,706.25
TOTAL LABOUR COST : \$ 1,130.00
TOTAL REPAIR COST : \$ 3,836.25

Adrian G
2/s 31/01/23.
02 hrs

Total: 935.75
4/s: 750. ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: