



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|---|----------------|
| HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: OH VALE | | Ref: CS/ASM23000554/Kqp3e2 Date: 02/02/2023 Code: HSB | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHB 6369S | Veh. Inspected | SJN 265K |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | S3M04I0W | Excess (\$) | 0.00 |
| Assign From | OH VALE | Assign Date | 17/01/2023 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA VIOS (A) | c.c | 1497 |
| Engine No. | HIDDEN | Year of Reg. | 2009 |
| Chassis No. | MR053HY9305090415 | Colour | METALLIC GREEN |
| Odometer | 242160 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195/55 R15 | MICHELIN | 9 mm |
| L/H Front Tyre | 195/55 R15 | MICHELIN | 9 mm |
| R/H Rear Tyre | 195/55 R15 | GOODYEAR | 9 mm |
| L/H Rear Tyre | 195/55 R15 | GOODYEAR | 9 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 15/01/2023 | Inspection Date | 17/01/2023 |
| Survey held at | EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | |