

Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD

DATE: 16/1/2023

Survey details

| | |
|---------------------|---------------------------------|
| Date of loss | 14/1/2023 |
| Date of appointment | 17/1/2023 |
| Date of survey | 19/1/2023 |
| Location of survey | RIVERVIEW AUTO SERVICES PTE LTD |
| | |

Vehicle Details:

| | |
|----------------------|----------------|
| Claim Type: | THIRD PARTY |
| Vehicle number | SLP 5059Y |
| Make and Model | HONDA JAZZ (A) |
| Date of registration | 7/6/2017 |
| Excess | |
| Market Value | \$62,000.00 |
| Part Rebate | \$31,218.00 |
| Nett Loss | \$30,782.00 |

Repair details

| | |
|------------------|------------|
| Initial Estimate | \$8,841.70 |
|------------------|------------|

Proposed/Revised repair cost:

| | |
|--------------------------|--------------|
| Parts | \$2,187.70 |
| "Check items (Estimated) | |
| Labour | \$1,430.00 |
| Total | \$3,617.70 |
| Lump Sum (Estimated) | \$2,900.00 |
| | |
| Number of days of repair | 5 days (est) |

Remarks:

| |
|---|
| The vehicle sustained damages at the rear portion |
| Damages Consistent |
| Please note that the preliminary advise amount (Revised and checked) stated are subject to consistency check, part prices and labour cost . |