



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SJP26Z

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT  
8 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER 3  
SINGAPORE 038988  
68299199

WIP No

62406

Reg No/Reg Date

SJP26Z / 13/01/2020

Date In/Mileage

20/01/2023/ 65168

Chassis No

WDD2221622A4847412

Engine No

27682431038647

Make/Model

MB/MB S 320 SEDAN LONG

Colour/Trim

028 897 Ruby Black / 048 801 Nappa Black

Vehicle & Document Information

| Account No | Terms  | Date/Time Printed | CSE | Operator          |
|------------|--------|-------------------|-----|-------------------|
| WN000512   | Credit | 06/05/2023/ 15:15 | CH  | 371 / Go Chee Han |

| Description of Goods / Services                | Qty  | Unit Price | Disc% | Amount |
|--|------|------------|-------|--------|
| M BPN SUN                                      |      |            |       |        |
| POLICY NO/ACC DATE : DMPG23000269 // 13-1-2023 |      |            |       |        |
| TOW IN/EXCESS : 13-1-2023 // \$1000            |      |            |       |        |
| DATE IN/DATE SURVEY: 17-1-2023 // RASUL - LKK  |      |            |       |        |
| BY/AUTHORIZED ON : 19-1-2023 // HUEY YON - LKK |      |            |       |        |
| X RH/FRONT WINDOW GUIDE RAIL                   | 1.00 | 231.52     | 00.00 | 231.52 |
| X RH/FRONT DOOR SEALING FRAME                  | 1.00 | 57.05      | 00.00 | 57.05  |
| X COMBINATION NUT                              | 3.00 | 5.09       | 00.00 | 15.27  |
| X RH/FRONT COVER, WHEEL ARCH                   | 1.00 | 263.25     | 00.00 | 263.25 |
| X MOUNTING RAIL                                | 1.00 | 15.39      | 00.00 | 15.39  |
| X MOUNTING CLIP                                | 1.00 | 9.64       | 00.00 | 9.64   |
| X TRIM CLIP                                    | 4.00 | 13.19      | 00.00 | 52.76  |

Confirmed & accepted by

8% GST on **Nett 644.88**  
**644.88** **51.59**

**Total Payable 696.47**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG