



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR23000565/Rqy3e2 Date: 03/03/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 1801T	Veh. Inspected	SKS 2951L
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/01/23/2022	Excess (\$)	0.00
Assign From	ASHLENE LEE	Assign Date	17/01/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLA200 S/R	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDC1569432J020338	Colour	GREY
Odometer	112415 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/45 R19	GOODYEAR	6 mm
L/H Front Tyre	235/45 R19	GOODYEAR	6 mm
R/H Rear Tyre	235/45 R19	GOODYEAR	6 mm
L/H Rear Tyre	235/45 R19	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/01/2023	Inspection Date	06/02/2023
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	