





# MOHAMED AUTOMOBILE

38, Woodlands Industrial Park E-1, #01-16, Singapore 757700  
 Tel : 6468 1322 Fax : 6468 1376  
 Email : mohdauto@yahoo.com  
 Reg No : 53326419 K

To: LONPAC Insurance Bhd

18<sup>th</sup> January 2023

Attn: Motor Property Claims

Dear Sir,

## Accident Involving SLF-5921-K & GBG-624-P (03<sup>rd</sup> Jan 2023)

Quotation for the repair of Vehicle Number SLF-5921-K

No	Description (Part Rplacement)	Unit	Unit price	Amount
1.	Bootlid	1	890.00	890.00 <i>hl</i>
	Bootlid Logo (Toyota)	1	68.00	68.00 <i>ulr</i>
2.	Bootlid handle	1	165.00	165.00 <i>?</i>
3.	Bootlid Hydraulic Cylinders L & R	2	186.00	372.00 <i>x</i>
5.	Bootlid lock cylinder	1	197.00	197.00 <i>bx</i>
6.	Bootlid number plate lamp L/R	2	46.00	92.00 <i>x</i>
7.	Bootlid inner trim	1	259.00	259.00 <i>x</i>
8.	Bootlid hinge L/R	2	87.00	174.00 <i>x</i>
9.	Bootlid lock	1	186.00	186.00 <i>bt</i>
10.	Bootlid lock catch	1	93.00	93.00 <i>x</i>
11.	Bootlid weatherstip	1	180.00	180.00 <i>fn</i>
	Bootlid wind screen	1	480.00	480.00 <i>x</i>
14.	Rear bumper	1	685.00	685.00 <i>de</i>
15.	Rear bumper reflector L/R	2	115.00	230.00 <i>x</i>
16.	Rear bumper retainer L/R	2	65.80	131.60 <i>?</i>
17.	Rear bumper reinforcement bar	1	376.00	376.00 <i>?</i>
20.	End panel	1	788.00	788.00 <i>R, Re</i>
21.	End panel garnish	1	136.70	136.70 <i>de</i>
22.	Spare wheel panel	1	681.00	681.00 <i>R, Re</i>
Total				\$ 6,184.30
Less 25 %				\$ 1,546.07
Total				\$ 4,638.22

	S/Nett items			
1.	Rear bumper reverse sensor	1	280.00	280.00 200 mm
2.	Bootlid inner trim clips	1	50.00	50.00 X
3.	Tail lamp panel sealant	1	120.00	120.00 X
4.	Rear bumper clips	1	50.00	50.00 300 -
5.	End panel sealant	1	80.00	80.00 X
6.	End panel garnish clips	1	50.00	50.00 200
7.	Spare wheel panel sealant	1	120.00	120.00 X
	<b>Total</b>			<b>\$ 750.00</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


	LABOUR	
1.	To remove and refit rear electrical wiring, replaced, damaged by repair test for proper functioning	100.00 30
2.	To remove and refit rear cushion seats, interior upholstery to facilitate the repairs.	120.00 60
3.	To remove and refit rear bumper sensor.	80.00 30
4.	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original using power tools.	1,800.00 600
5.	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	1,800.00 600
6.	To apply undercoating on the repaired and replace panels for rust protection.	120.00 30
	<b>Total Amount</b>	<b>\$4,020.00</b>

Taufik 97495749 / 62563561  
 Wp' 18/1/23 @ 1315  
 taufik@lkhauto.com  
 5 days  
 Lumpsum Resum after repair.

Parts Replacement	\$ 4,638.30
Special Nett items	\$ 750.00
Labour	\$ 4,020.00
Total Amount	\$ 9,408.30

In Singapore Dollars: NINE THOUSAND FOUR HUNDRED EIGHT AND CENTS  
THIRTY ONLY

Mohamed Automobile



Ameer Ali

Mobile: 9730-9393

copy



## SINGAPORE ACCIDENT STATEMENT

(Rapi) (SQ21)

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	04/01/2023 17:30 (SGT)
Reported by	Driver
Date of Accident	03/01/2023 15:03 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE TOWARDS TUAS AFTER PAYA LEBAR FLYOVER
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF5921K
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	MOHAMED AUTOMOBILE
Company Reg No	53326419K
Email Address	mohdauto@yahoo.com
Mobile Phone No	(Phone) +65-64681322
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	SIENTA 1.5X A
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1496

### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5115504521-02

### DRIVER

Name of Driver	MOHAMED RAPI BIN HAMID
NRIC No	S7103790H
Date Of Birth	11/02/1971
Occupation	Outdoor

Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt. Phone Number

Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

24/08/1993

29 YEARS AND 5 MONTHS

Male

(Phone) +65-82531243

mohdauto@yahoo.com

BLK 463A SEMBAWANG DRIVE #02-363

751463

No

Hirer

No

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Weather Conditions

Road Surface

Collision - Head to Rear

AFTER RAIN

Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No

Number of vehicles involved in the accident

2

Was anybody injured in the Accident?

No

Was any injured conveyed to hospital by ambulance?

-

Was any other vehicle or property damaged?

Yes

Number of Passengers (Including Driver)

1

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No

Translator's name

-

Translator's ID

-

Translator's phone number

-

Translator's email

-

Original language used in the statement

-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?

No

Was notice of intended Prosecution given?

No

If yes, against whom?

-

#### CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED (REPAIR BY OTHER WORKSHOP)

#### ATTACHMENT(S)

Are accident photos available for attachment?

Yes

Was there any video captured by Car Camera?

No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number

GBG624P

Vehicle Manufacturer

-

Vehicle Model

-

Vehicle Variant

-

Vehicle Colour

-

Vehicle Category

Commercial vehicle

Name of Driver

NG TECK CHUAN

NRIC No

S1476760F

Contact Number

(Phone) +65-96235482

Address

-

Address complement

-

Postcode

-

Insurance Company Name

-

Nature Of Damage

-

Details of property damaged in accident

-

No. Of Passenger (Including Driver)

-

SLF 5921K

JN/CMF

03/01/23 3:03 PM

SKETCH PLAN

IMPORTANT NOTICE

1. This form is to be filled out by the insured or the policyholder or the insured's representative.
2. The form is to be filled out by the insured or the policyholder or the insured's representative.
3. The form is to be filled out by the insured or the policyholder or the insured's representative.
4. The form is to be filled out by the insured or the policyholder or the insured's representative.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. The report will be forwarded by the insurers to the GSA Records Management Centre established by the GSA for the purpose of maintaining a record of all motor vehicle accidents and the details of the report will for a fee be made available upon request to the insured or the policyholder or the insured's representative.
7. By the completion of this form, the insured or the policyholder or the insured's representative consents to the recording of this report at the centre and to the use of the report for the purposes mentioned.

Consent under the Personal Data Protection Act (PDPA)


I/We hereby agree and consent that

(1) My/our firm, my/our shop and the General Insurance Association of Singapore ("GIA") may use, process, store, transfer, disclose, disseminate, publish, process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer collectively the "Personal Information"] and disclose and transfer such Personal Information to all insured and insured vehicles involved in this accident (all insurers) who have insured vehicles involved in the accident and all be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/body (such as the police), for the purposes of (a) investigating the accident and/or my claims, (b) carrying out and/or dealing with my instructions or responding to any enquiries by me, (c) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/s and packages), and/or (d) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

My/our firm(s) who have insured vehicles involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

for my Personal Information may be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature, Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessing by Reporting Officer/Personnel (Name as in NRIC/ID card)

Sketch Plan






On 3/20/23 at about 1503hrs, travelling along PIE Toward Tuas after Paya Lebar flyover. Suddenly a vehicle GBG 624P hit my back vehicle during stopping time as it was very heavy flow of traffic.

It was during slowing moving. No body injured and the vehicle dented at the back rear.

## Declarations

Let denote the  $H$ -invariant  $\mathbb{P}^1$ -bundles are the same in every respect



12. The following are the results of the first 100 trials of the experiment:

4/01/23

[illegible]