

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHC3032C/16/01/2023 14:19	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	20.00	0.00	500 / *481.10 FL ✓
2	10		*FRT BUMPER CLIPS	20.00	0.00	NEL ✓ *22.00 FL ✓
3	1		*FRT BUMPER SIDE BRACKET RH	20.00	0.00	1.1XNN ✓ *35.00 FL ✓
4	1		*FRT FENDER RH	20.00	0.00	Denat ✓ *588.80 FL ✓
5	1		*FRT FENDER EMBLE RH	20.00	0.00	NEL ✓ *26.60 FL ✓
6	1		*FRT SIDE MIRROR RH	20.00	0.00	500 ✓ *1,691.70 FL 1391.7 ✓
7	1		*FRT DOOR ASSY RH	20.00	0.00	Denat ✓ *1,797.20 FL ✓
8	1		*FRT DOOR COMFORT LOGO	0.00	0.00	NEL ✓ *75.00 F ✓
9	1		*ADVERTISEMENT LOGO - FENDER	0.00	0.00	NEL ✓ *100.00 F ✓
10	1		*ADVERTISEMENT LOGO - DOOR	0.00	0.00	NEL ✓ *100.00 F ✓

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,917.40
- List Item Discount on L Items (S\$)	928.48
Total Parts (S\$)	3,988.92

ComfortDelGro Engineering Pte Ltd/SHC3032C/16/01/2023 14:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Front Side mirror - \$1391.70

Parts = 4307.40

20% = 861.48

= 3445.92

+ Net +

= 3720.92 //

F = 4582.40

20% = 916.48

= 3665.92

3720.92

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

Sub Total (S\$)

11.00

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

2 SPRAYPAINT

3 TUFF KOTE

4 CHECK WIRING

5 TRANSFER DOOR PARTS

New

New

New

New

New

1,200.00 1050

1,000.00 750

50.00 XNN

50.00 30

120.00 80

Gross Labour Cost (S\$)

2,420.00

ComfortDelGro Engineering Pte Ltd/SHC3032C/16/01/2023 14:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Total = 5366.92

~5350

3 days

1st fm 4/5 18/1/23 4.30pm

= 5641.92

206 = 1128.38

= 4500

4500

206 = 1128.38

=

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: