

(08/11/13) wef

ASS. REC. BY: James

REF:

CS/CT123000611/RNP3

0100

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 6182B

at Workshop m/s SNH AH TEE

of 3, PUNAR ROAD NORTH #01-18

Insured: CTI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition) 10-2pm

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 76K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLS 6182B Yr Regn: 2017 / SEP

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA SIENNA 1.5 CVT STD c.c. 1496

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 129186 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MHFZ28H3900041908

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm R/Bal. 6 mm


L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 12/01/23 D.O.I. 23/02/23

Survey held at SNH AH TEE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

Repair Limit - 44K

We will be advising our principal a cost of repair P/P \$2,298.75 /- with 04 days  
(red, \$2186.55, 48%)

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER SINGAPORE 079909  
MOTOR CLAIMS DEPT  
ATTENTION :  
CONTACT : 62222366 FAX NO: 62221033

EST/QUOTE NO. SQ007889

DATE 16/02/2023  
ACCIDENT DATE : 13/01/2023  
VEHICLE NO : SLS6182B  
CHASSIS/ENG.NO : MHFZ28H3900041908  
VEHICLE MODEL : TOYOTA SIENTA  
CLAIM NO : SNM23D200394/C02  
POLICY NO :  
REMARK : 6182 CHINA TP AGST  
PC6569G

| S/N.                    | QTY | UNIT | DESCRIPTION                      | PRICE    | DISC % | DISC/MARKUP | TOTAL AMT |
|-------------------------|-----|------|----------------------------------|----------|--------|-------------|-----------|
| <b>** LIST PRICE **</b> |     |      |                                  |          |        |             |           |
| 1                       | 1   | PC   | REAR BUMPER repair               | 455.00   | 25     | 341.25      | 341.25    |
| 2                       | 1   | PC   | REAR BUMPER LOWER CTR GARNISH de | 178.00   | 25     | 133.50      | 133.50    |
| 3                       | 1   | PC   | REAR BUMPER TOW COVER LH X       | 32.00    | 25     | 24.00       | 24.00     |
| 4                       | 10  | PC   | REAR BUMPER CLIPS X              | 5.50     | 25     | 4.13        | 41.30     |
| 5                       | 1   | PC   | REAR FOGLAMP ASSY X              | 195.00   | 25     | 146.25      | 146.25    |
| 6                       | 1   | PC   | REAR FOGLAMP BRACKET X           | 55.00    | 25     | 41.25       | 41.25     |
| 7                       | 1   | PC   | REAR BOOTLID bt                  | 1,100.00 | 25     | 825.00      | 825.00    |
| 8                       | 1   | PC   | REAR BOOT CENTER TRIM X          | 270.00   | 25     | 202.50      | 202.50    |
| 9                       | 1   | PC   | REAR BOOT EMBLEM ne              | 58.00    | 25     | 43.50       | 43.50     |
| 10                      | 1   | PC   | REAR BOOT 'SIENTA' STICKER r     | 59.00    | 25     | 44.25       | 44.25     |
| 11                      | 1   | PC   | REAR BOOT 'G' STICKER m          | 55.00    | 25     | 41.25       | 41.25     |
| 12                      | 1   | PC   | REAR WINDSCREEN MOUDLING m       | 715.00   | 25     | 536.25      | 536.25    |

SUB-TOTAL: 2,420.30

**\*\* SPECIAL NETT PRICE \*\***

|   |   |    |                           |        |  |           |          |
|---|---|----|---------------------------|--------|--|-----------|----------|
| 1 | 1 | PC | REAR WINDSCREEN SEALANT m | 40.00  |  | 40.00     | 30 40.00 |
| 2 | 1 | PC | REAR NUMBER PLATE X       | 45.00  |  | 45.00     | 45.00    |
| 3 | 1 | PC | REAR REVERSE SENSOR X     | 280.00 |  | 280.00    | 280.00   |
|   |   |    |                           |        |  | SUB-TOTAL | 365.00   |

JOYCE

PAGE: 1 of 2

8%

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.  
Quotation is only valid for 14 days.

## EST/QUOTE NO. SQ007889

DATE 16/02/2023  
ACCIDENT DATE : 13/01/2023  
VEHICLE NO : SLS6182B  
CHASSIS/ENG.NO : MHFZ28H3900041908  
VEHICLE MODEL : TOYOTA SIENTA  
CLAIM NO : SNM23D200394/C02  
POLICY NO :  
REMARK : 6182 CHINA TP AGST  
PC6569G

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON ROAD #16-00

SPRINGLEAF TOWER SINGAPORE 079909

MOTOR CLAIMS DEPT

ATTENTION :

CONTACT : 62222366

FAX NO: 62221033

| S/N. | QTY | UNIT | DESCRIPTION | PRICE | DISC % | DISC/MARKUP | TOTAL AMT |
|------|-----|------|-------------|-------|--------|-------------|-----------|
|------|-----|------|-------------|-------|--------|-------------|-----------|

### \*\* WORK LABOUR \*\*

|                                            |        |                |                   |
|--------------------------------------------|--------|----------------|-------------------|
| TO KNOCK,WELD,REMOVE & REPLACE ABOVE PARTS | 600.00 | <del>400</del> | <del>600.00</del> |
| TO SPRAY PAINTING ON AFFECTED AREAS        | 750.00 | <del>400</del> | <del>750.00</del> |
| TO CHECK WIRING                            | 30.00  | X              | 30.00             |
| TO REMOVE AND REFIX RR WINDSCREEN          | 120.00 |                | 120.00            |
| TO DIAGNOSE & RESET FAULT CODE             | 120.00 | 60             | <del>120.00</del> |
| TO REMOVE & REFIX REAR TRIMS               | 80.00  | 40             | <del>80.00</del>  |
| SUB-TOTAL                                  |        |                | 1,700.00          |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Panel*  
*Hp 9001w 68*  
*4 days*  
*7/1*  
*23/02/23 @ 1320*  
*Resy before paint*

JOYCE

PAGE: 2 of 2

SUB-TOTAL : S\$ 4,485.30  
ADD GST. 8% S\$ 358.82  
GRAND TOTAL : S\$ 4,844.12

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.  
Quotation is only valid for 14 days.

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type:                      | Singapore NRIC                       |
| Owner ID:                           | 010D                                 |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.:                        | SL56182B                             |
| Vehicle to be Exported:             | No                                   |
| Intended Deregistration Date:       | 26 Feb 2023                          |
| Vehicle Make:                       | TOYOTA                               |
| Vehicle Model:                      | SIENTA 1.5 CVT STD                   |
| Primary Colour:                     | Grey                                 |
| Manufacturing Year:                 | 2017                                 |
| Engine No.:                         | 2NRX216523                           |
| Chassis No.:                        | MHFZ28H3900041908                    |
| Maximum Power Output:               | 79.0 kW (105 bhp)                    |
| Open Market Value:                  | \$17,129.00                          |
| Original Registration Date:         | 28 Sep 2017                          |
| First Registration Date:            | 28 Sep 2017                          |
| Transfer Count:                     | 0                                    |
| Actual ARF Paid:                    | \$17,129.00                          |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility:                   | Yes                                  |
| PARF Eligibility Expiry Date:       | 27 Sep 2027                          |
| PARF Rebate Amount:                 | \$11,990.00                          |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date:                    | 27 Sep 2027                          |
| COE Category:                       | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                  | 10                                   |
| QP Paid:                            | \$42,902.00                          |
| COE Rebate Amount:                  | \$19,675.00                          |
| <b>Total Rebate Amount:</b>         | <b>\$31,665.00</b>                   |

# Toyota Sienta Hybrid 1.5A G

**Overview**

Financial

Accessories

Similar

Research

Photos

Map



## HUA YANG CREDIT PTE LTD



|              |                                                                |              |                                            |
|--------------|----------------------------------------------------------------|--------------|--------------------------------------------|
| Price        | \$79,800                                                       |              |                                            |
| Depreciation | \$16,240 /yr<br><a href="#">View models with similar depre</a> | Reg Date     | 30-Nov-2017<br>(4yrs 9mths 3days COE left) |
| Mileage      | 62,000 km (11.8k /yr)                                          | Manufactured | 2017                                       |
| Road Tax     | \$682 /yr                                                      | Transmission | Auto                                       |
| Dereg Value  | \$23,869 as of today ( <a href="#">change</a> )                | Fuel Type    | Petrol-Electric                            |
| COE          | \$42,801                                                       | OMV          | \$24,253                                   |
| Engine Cap   | 1,496 cc                                                       | ARF          | \$5,000                                    |
| Curb Weight  | 1,380 kg                                                       | Power        | 73.0 kW (97 bhp)                           |