



**Main Office :** No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 5891

**Service Centre :** Block 100B, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0086864-2

**Mova Spray Centre**  
2K Oven Spray Painting System

**Power-M Automotive Pte Ltd**  
Specialise In Car Air-con Services,  
Car Audio & Hi-Fi System.

**Hilton Car Rental Centre**

**Hilton Auto Trading**  
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

#### PARTICULARS OF CLAIM

|                               |                                            |                       |                   |
|-------------------------------|--------------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                            | Ref. No:              |                   |
| Policy No:                    | DMCG22005300                               | Date of Loss:         | 13/01/2023        |
| Vehicle Reg. No.:             | <b>XE2928A</b>                             | Driveable?            |                   |
| Driver Age/Info:              |                                            | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                         | Third Party Involved? | YES               |
| Insured/Claimant:             | CA TRANSPORTATION & WAREHOUSING<br>PTE LTD |                       |                   |
| Make/Model:                   | UD TRUCKS GKB85ELDHNT, 10.8 D (M)          | Vehicle Reg. Date:    | 08/05/2017        |
| Vehicle Colour:               | WHITE                                      | Chassis No:           | JNCM1F1AXHU019629 |
| Engine No:                    | GH11742602                                 |                       |                   |
| Odometer:                     | 312092 KM                                  |                       |                   |
| Paint Type:                   |                                            |                       |                   |
| Total Loss?                   | NO                                         |                       |                   |
| Est. Duration of Repair (day) | 10                                         |                       |                   |
| Present Location:             | MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)      |                       |                   |

#### COST OF CLAIMS

|                           | Amount           |
|---------------------------|------------------|
| Parts                     | 14,188.90        |
| Miscellaneous Items       | 220.00           |
| Labour                    | 2,840.00         |
| Paintwork Labour          | 0.00             |
| Towing                    | 0.00             |
| <b>Gross Total (\$\$)</b> | <b>17,248.90</b> |
| <b>+ GST 8.00% (\$\$)</b> | <b>1,379.91</b>  |
| <b>Nett Amount (\$\$)</b> | <b>18,628.81</b> |

This claim is handled by: BRIAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 18 Jan 2023)

Parts: N/A UD TRUCKS GKB85ELDHNT 10.8 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE2928A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                                 | %Disc | %Depr | Amount               |
|-----|-----|----------|---------------------------------------------|-------|-------|----------------------|
| 1   | 1   |          | *GRILLE ASSY TOP <i>repair</i>              | 0.00  | 0.00  | *485.00 F            |
| 2   | 1   |          | *GRILLE ASSY LOWER <i>cm</i>                | 0.00  | 0.00  | *450.00 F            |
| 3   | 1   |          | *FRONT BUMPER STEP CENTER <i>cut</i>        | 0.00  | 0.00  | *25.00 F             |
| 4   | 1   |          | *FRONT BUMPER STEP LH <i>cm</i>             | 0.00  | 0.00  | *51.00 F             |
| 5   | 1   |          | *CORNER PANEL LOWER COVER LH <i>mm? XAN</i> | 0.00  | 0.00  | *20.00 F             |
| 6   | 1   |          | *FRONT BUMPER BASE <i>bt</i>                | 0.00  | 0.00  | *950.00 F            |
| 7   | 1   |          | *FRONT BUMPER CENTER <i>bt</i>              | 0.00  | 0.00  | *500.00 F            |
| 8   | 1   |          | *FRONT BUMPER CORNER <i>bt</i>              | 0.00  | 0.00  | *450.00 F            |
| 9   | 1   |          | *FRONT BUMPER CORNER, END PIECES <i>cm</i>  | 0.00  | 0.00  | *65.00 F             |
| 10  | 1   |          | *FRONT BUMPER GRILLE, CTR <i>mis</i>        | 0.00  | 0.00  | *137.50 F            |
| 11  | 1   |          | *FRONT BUMPER GRILLE LH <i>mm</i>           | 0.00  | 0.00  | *65.00 F             |
| 12  | 1   |          | *SIDE STEP <i>cm</i>                        | 0.00  | 0.00  | *120.00 F            |
| 13  | 1   |          | *SIDE STEP REFLECTOR <i>mm</i>              | 0.00  | 0.00  | *15.00 F             |
| 14  | 1   |          | *SIDE STEP BACK COVER <i>cm</i>             | 0.00  | 0.00  | *85.00 F             |
| 15  | 1   |          | *SIDE STEP BRKT <i>bt-lpc</i>               | 0.00  | 0.00  | *500.00 F <i>280</i> |
| 16  | 1   |          | *HEADLAMP? <i>cm</i>                        | 0.00  | 0.00  | *600.00 F            |
| 17  | 1   |          | *FRONT LAMP <i>cm</i>                       | 0.00  | 0.00  | *85.00 F             |
| 18  | 1   |          | *FOG LAMP <i>cm</i>                         | 0.00  | 0.00  | *90.00 F             |
| 19  | 1   |          | *UNDERNEATH COVER, FRONT <i>cm</i>          | 0.00  | 0.00  | *258.00 F            |
| 20  | 1   |          | *FAN SHROUD <i>cm</i>                       | 0.00  | 0.00  | *300.00 F            |
| 21  | 1   |          | *AIR COOLER <i>bt</i>                       | 0.00  | 0.00  | *2,089.00 F          |
| 22  | 1   |          | *COOLANT HOSE, TOP <i>cut</i>               | 0.00  | 0.00  | *95.00 F             |
| 23  | 1   |          | *RADIATOR <i>bt</i>                         | 0.00  | 0.00  | *1,400.00 F          |
| 24  | 1   |          | *NET RADIATOR <i>repair</i>                 | 0.00  | 0.00  | *650.00 F            |
| 25  | 1   |          | *FAN ASSY <i>cut</i>                        | 0.00  | 0.00  | *1,700.00 F          |
| 26  | 1   |          | *RADIATOR SUPPORT BRKT <i>bt</i>            | 0.00  | 0.00  | *45.00 F             |
| 27  | 1   |          | *FAN SHROUD SUPPORT <i>bt</i>               | 0.00  | 0.00  | *350.00 F            |
| 28  | 1   |          | *FAN SHROUD, INNER <i>cm</i>                | 0.00  | 0.00  | *1,058.50 F          |

F=Franchise part.

11264

|                                    |                  |
|------------------------------------|------------------|
| Sub Total (S\$)                    | 12,899.00        |
| + Margin on L,N Items 10.00% (S\$) | 1,289.90         |
| <b>Total Parts (S\$)</b>           | <b>14,188.90</b> |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars                   | Amount |
|----------------------------|-----|-------------------------------|--------|
| <u>Miscellaneous Items</u> |     |                               |        |
| 1                          | 3   | COOLANT <i>rec /</i>          | 180.00 |
| 2                          | 1   | FRONT NUMBER PLATE <i>51-</i> | 40.00  |
| Sub Total (S\$)            |     |                               | 220.00 |

## Estimates on Labour

| No                      | Particulars                                                                        | Lab.Type        | Amount             |
|-------------------------|------------------------------------------------------------------------------------|-----------------|--------------------|
| <u>Labour Items</u>     |                                                                                    |                 |                    |
| 1                       | TO KNOCK FRONT BUMPER BRACKET & REPLACE ACCIDENT DAMAGED PARTS RELATED TO ACCIDENT | New <i>500</i>  | <del>600.00</del>  |
| 2                       | TO SPRAY PAINT ON FRONT GRILLE, BUMPER CENTER, BUMPER CORNER, SIDE STEP BACK COVER | New <i>1000</i> | <del>1700.00</del> |
| 3                       | TO CRANE OUT THE RADIATOR ASSY, TURBO INTERCOOLER <i>photo</i>                     | New <i>300</i>  | <del>500.00</del>  |
| 4                       | TO ADJUST FOCUS HEADLAMP AND CHECK ALL LIGHTING FUNCTIONING                        | New             | <del>40.00</del>   |
| Gross Labour Cost (S\$) |                                                                                    |                 | 2,840.00           |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS  
< END OF ESTIMATES >

Parts: 12390.40

S/N: 220

L: 1840

Total: 14450.40

Ys: 11550 #

*Refine*

*Hp 90010068*

*5 days*

*4/5*

*19/01/23 @ 1540*

*EXCESS: 1500*

*REVERT*

*Resy after repair*